





report date: 2024-03-29

General information

Make	FORD
Model	FOCUS CC2
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-02

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-05

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-04-13
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #17	2024-04-09 08:49
MOT test number	172545642905
Result	✓ Passed
Next expiry date	2025-04-13

MOT #16		2023-04-14 12:01
MOT test	number	852263681889
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Car only starts sometimes	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Bonnet very tricky to open	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2022-01-31 14:26 **MOT** test number 900882160282 Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail

MOT #13

MOT test number

425067232139

Result

✓ Passed

MOT #12 2021-02-19 14:57

MOT test number 680089868717

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/13



Result

YS09DWG

report date: 2024-03-29

✓ Passed

MOT #11 2020-02-21 15:39

MOT test number 686689090943

Result ✓ Passed

MOT #10 2019-02-18 11:40

MOT test number 578358278089

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre slightly damaged Slight damage to outer wall. (5.2.3 (d) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2018-02-19 17:37

MOT test number 298737196888

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8 2018-02-19 12:27

MOT test number 236210317713

Result X Failed

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7 2017-02-06 14:31

MOT test number 538546490509

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #6	2016-01-20 09:56
--------	------------------

MOT test number 280747995788

MOT #5 2016-01-12 13:20

MOT test number 551181043109

Result X Failed

Fail Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords edge of tyre (4.1.D.1a)

Fail Nearside Rear Outer Tyre has ply or cords exposed wall has a cut deep reached cords (4.1.D.1b)

MOT #4 2015-02-16 08:49

MOT test number 525037445081

Result ✓ Passed

MOT #3 2014-02-19 13:30

MOT test number 709670354027

Result ✓ Passed

MOT #2 2013-02-20 16:30

MOT test number 387381553085

Result \rightarrow Passed

MOT #1 2012-06-27 16:09

MOT test number 636829672113

Result

Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	I
INMAR	nictory
	IIISLUIV

o mile mesery		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	OK ON THE STATE OF	
Plate since		
Current registration	UK WEST	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-06-30
Last registration	2024-04-09
Complete history	See info



Registration #1	2009-06-30	17 mi
Registration #2	2012-06-27	37.358 mi
Registration #3	2013-02-20	39.647 mi
Registration #4	2014-02-19	43.740 mi
Registration #5	2015-02-16	46.941 mi
Registration #6	2016-01-12	49.950 mi
Registration #7	2016-01-20	49.965 mi
Registration #8	2017-02-06	53.902 mi
Registration #9	2018-02-19	57.012 mi
Registration #10	2018-02-19	57.012 mi
Registration #11		91,709 esi
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1991 mm
Height	1448 mm
Length	4509 mm
Wheel base	2640 mm
Kerb weight	1543 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13