





report date: 2024-03-29

## General information

Make	KIA
Model	VENGA CRDI 3 ECODYNAMICS
Colour	White
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

#### Entry 2

Date 2021-07-24

Pictures 18

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-22

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #8		2023-07-17 11:49
MOT test	number	288473871945
Result		✓ Passed
Next expi	ry date	2024-07-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge just above limit (5.2	2.3 (e))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #7		2022-07-11 11:30
MOT test	number	661816742401
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



Result

LD15MRO report date: 2024-03-29

× Failed

**MOT #6** 2021-06-22 14:19

MOT test number 158947300874

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Items removed from driver's view prior to test

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2021-06-22 12:24

MOT test number 123650212954

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Items removed from driver's view prior to test

**MOT #4** 2020-06-30 08:14

**MOT test number** 658055149845

Result \rightarrow Passed


Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



LD15MRO

report date: 2024-03-29



MOT #1	2018-05-22 08:15
MOT test number	155904217662
Result	<b>√</b> Passed
Advice Offside Rear Nail in tyre	
Advice Offside Front Nail in tyre	

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	16 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report h	
manage of the same	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE UK
Plate since	
Current registration	NIE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-29
Last registration	2023-07-17
Complete history	See info



Registration #1	2015-05-29	18 mi
Registration #2	2018-05-22	19.731 mi
Registration #3	2019-05-20	28.092 mi
Registration #4	2019-05-20	28.094 mi
Registration #5	2020-06-30	36.552 mi
Registration #6	2021-06-22	42.157 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		77.777 mg

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4075 mm
Wheel base	2615 mm
Kerb weight	1455 kg
Max. allowed weight	1810 kg

## Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	2 12/12

Number of axles 2

**Engine number** D4FBFZ014187