





General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	Blue
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel







Internet history

E	ntrv	1

Date

2021-07-27

View report

4

Pictures

Listing price



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	8

MOT #16	2023-08-31 09:31
MOT test number	716257161088
Result	✓ Passed
Next expiry date	2024-08-31

MOT #15	2022-08-31 11:05
MOT test number	374252722891
Result	Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2021-08-26 14:47
MOT test number	405027599085
Result	✓ Passed

MOT #13		2020-09-01 16:40
MOT test	number	574207363269
Result		✓ Passed
Advice	Wishbone bushes worn	
Advice	Handbrake lever has slight reserve travel	
Advice	Oil leaks	





MOT #12		2020-09-01 16:40
MOT test number		952824145952
Result		🗙 Failed
Advice Oil leaks		
Pass with rectification	Rear Direction indicator adversely affected by the operation of	another lamp
(4.4.3 (b))		
Advice Wishbone bushe	es worn	
Advice Handbrake level	r has slight reserve travel	
NOT #11		2010 05 17 10 02
MOT #11		2019-05-17 10:03
MOT test number		800112187372
Result		✓ Passed
Advice Front brake pad	s wearing low	
MOT #10		2019-05-17 10:03
MOT test number		170187260387
Result		🗙 Failed
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Front brake pad	s wearing low	

МОТ #9	2018-05-29 11:46
MOT test number	328185648722
Result	✓ Passed



MOT #8	2018-05-18 14:10	
MOT test number	196608966687	
Result	× Failed	
Fail Offside Rear fog lamp not working (1.	3.2b)	
Fail Windscreen washer provides insufficient	ent washer liquid (8.2.3)	
Fail Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (4.1.E.2a)		

MOT #7	2017-05-22 09:05
MOT test number	740708260978
Result	✓ Passed
Advice Wipers smeary	

MOT #6		2016-05-20 09:29
MOT test	number	801974164862
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Child seats fitted to 7 of 13 passenger seats	

MOT #5	2015-05-11 13:00
MOT test number	396801935150
Result	✓ Passed

FV60TXH

report date: 2024-03-29



FV60	TXH
report date:	2024-03-29

MOT #4		2014-05-23 18:24
MOT test	number	269963644113
Result		✓ Passed
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.2b)	
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.2b)	

МОТ #3	2014-05-23 15:39
MOT test number	127423944187
Result	🗙 Failed
Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.2b)	
Fail Emergency exit sign missing (6.2.D.3)	
Fail Emergency exit window •break glass' hammer missing (6.2.D.2)	
Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.2b)	
Fail Nearside Emergency exit sign missing (6.2.D.3)	

MOT #2	2013-10-22 11:18
MOT test number	255475093260
Result	✓ Passed

MOT #1	2012-10-29 10:54
MOT test number	129453002356
Result	✓ Passed
Notice Test as none PSV	



FV60TXH report date: 2024-03-29

Tax & MOT check

√ Taxed	мот
Tax due: 1 March 2025	Expires: 31 August 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	31 August 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMP
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-12-13
Last registration	2023-08-31
Complete history	See info



Registration #2 2012-10-29 19.708 mi Registration #3 2013-10-22 27.243 mi Registration #4 2014-05-23 29.759 mi Registration #5 2014-05-23 29.759 mi Registration #6 2015-05-11 34.202 mi Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi			
Registration #3 2013-10-22 27.243 mi Registration #4 2014-05-23 29.759 mi Registration #5 2014-05-23 29.759 mi Registration #6 2015-05-11 34.202 mi Registration #7 2016-05-20 39.993 mi Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 T T Registration #11 T T Registration #12 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T	Registration #1	2010-12-13	19 mi
Registration #4 2014-05-23 29.759 mi Registration #5 2014-05-23 29.759 mi Registration #6 2015-05-11 34.202 mi Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 Image: Control of the state of the sta	Registration #2	2012-10-29	19.708 mi
Registration #5 2014-05-23 29.759 mi Registration #6 2015-05-11 34.202 mi Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 1 1 Registration #11 1 1 Registration #12 1 1 Registration #13 1 1 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1	Registration #3	2013-10-22	27.243 mi
Registration #6 2015-05-11 34.202 mi Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 1 1 Registration #10 1 1 Registration #11 1 1 Registration #12 1 1 Registration #13 1 1 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1	Registration #4	2014-05-23	29.759 mi
Registration #7 2016-05-20 39.993 mi Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 1 1 Registration #11 1 1 Registration #12 1 1 Registration #13 1 1 Registration #14 1 1 Registration #15 1 1 Registration #16 1 1	Registration #5	2014-05-23	29.759 mi
Registration #8 2017-05-22 44.387 mi Registration #9 2018-05-18 47.812 mi Registration #10 1000000000000000000000000000000000000	Registration #6	2015-05-11	34.202 mi
Registration #92018-05-1847.812 miRegistration #10Constration #10Constration #10Registration #11Constration #11Constration #12Registration #12Constration #13Constration #13Registration #14Constration #14Constration #15Registration #16Constration #17Constration #17	Registration #7	2016-05-20	39.993 mi
Registration #10Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17	Registration #8	2017-05-22	44.387 mi
Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17	Registration #9	2018-05-18	47.812 mi
Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17	Registration #10		11.777 est
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	Registration #11		11.777 esi
Registration #14Registration #15Registration #16Registration #17	Registration #12		11.777 est
Registration #15 Registration #16 Registration #17	Registration #13		11.777 esi
Registration #16 Registration #17	Registration #14		11.777 est
Registration #17	Registration #15		11.777 esi
	Registration #16		11.777 est
Registration #18	Registration #17		11.777 esi
	Registration #18		11.277 est





Dimensions & weight	
Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2015 kg
Additional information	
Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20411973