



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-10-23
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-22
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	34
Total items failed	12

MOT #15	2023-11-03 11:08
MOT test number	965945305284
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Undertray not fully secure (8.1.1 (b) (i))

**MOT #14**

2023-10-31 11:15

**MOT test number**

635603721975

**Result****✗ Failed**

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Undertray not fully secure (8.1.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))

**MOT #13**

2022-10-26 11:49

**MOT test number**

518368957866

**Result****✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2022-10-26 11:49

**MOT test number**

574902798362

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2021-09-22 15:51

**MOT test number**

531962256434

**Result**

✓ Passed

- Advice** Offside Front tyre wearing on inside edge
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))
- Advice** Sill covers fitted
- Advice** Under side of car slightly corroded
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm (5.3.4 (a) (i))
- Advice** Under trays fitted

**MOT #10**

2020-07-08 08:34

**MOT test number**

783926568734

**Result**

✓ Passed

- Advice** Under trays fitted
- Advice** Sill covers fitted

**MOT #9**

2019-04-01 11:13

**MOT test number**

118626790688

**Result**

✓ Passed

- Advice** Under tray fitted
- Advice** Sill covers fitted

**MOT #8** 2019-04-01 11:13**MOT test number** 563256685475**Result** ✗ Failed**Advice** Under tray fitted**Advice** Sill covers fitted**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2018-03-07 15:08**MOT test number** 525846178068**Result** ✓ Passed**Advice** Undertray fitted**Advice** Engine cover fitted**Advice** Sill covers fitted**MOT #6** 2018-03-07 15:08**MOT test number** 335657431182**Result** ✗ Failed**Advice** Engine cover fitted**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Sill covers fitted**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Undertray fitted**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2017-03-07 11:33**MOT test number** 850624516166**Result** ✓ Passed

**MOT #4** 2016-03-08 17:04**MOT test number** 836093897335**Result** ✓ Passed**Advice** Undertrays fitted obscuring some underside components**Advice** Engine covers fitted obscuring some engine bay components**MOT #3** 2015-03-10 11:51**MOT test number** 126439865431**Result** ✓ Passed**MOT #2** 2014-02-07 12:21**MOT test number** 469488134089**Result** ✓ Passed**MOT #1** 2014-02-06 10:10**MOT test number** 238607434069**Result** ✗ Failed**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
2 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	2 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-17
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2010-06-17	10 mi
Registration #2	2014-02-06	19.664 mi
Registration #3	2014-02-07	19.666 mi
Registration #4	2015-03-10	25.078 mi
Registration #5	2016-03-08	30.070 mi
Registration #6	2017-03-07	34.195 mi
Registration #7	2018-03-07	37.323 mi
Registration #8	2018-03-07	37.323 mi
Registration #9	2019-04-01	40.671 mi
Registration #10	2019-04-01	40.671 mi
Registration #11	2019-04-01	40.671 mi
Registration #12	2019-04-01	40.671 mi
Registration #13	2019-04-01	40.671 mi
Registration #14	2019-04-01	40.671 mi
Registration #15	2019-04-01	40.671 mi
Registration #16	2019-04-01	40.671 mi
Registration #17	2019-04-01	40.671 mi
Registration #18	2019-04-01	40.671 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1454 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	756877