




report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC BUSINESS EDITION TDCI
Colour	Grey
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	11.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-12-04
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-15
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	32
Total items failed	9

MOT #11 2023-11-27 13:20

MOT test number 429648638189

Result ✓ Passed

Next expiry date 2024-12-15

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-12-15 13:10

MOT test number 195345282056

Result ✓ Passed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #9**

2022-12-08 11:39

MOT test number

898769170355

Result**✗ Failed****Fail** Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**MOT #8**

2021-12-16 10:30

MOT test number

857288251435

Result**✓ Passed**

**MOT #7** 2021-12-08 13:56**MOT test number** 980895334676**Result** ✗ Failed**Advice** Offside Front Nail in tyre**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #6** 2021-01-11 12:06**MOT test number** 194440510495**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated Small hole in cv boot (6.1.7 (g) (i))**MOT #5** 2020-01-11 12:32**MOT test number** 766550454839**Result** ✓ Passed**MOT #4** 2020-01-11 09:55**MOT test number** 940032801133**Result** ✗ Failed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MOT #3** 2019-01-17 09:27**MOT test number** 102034211554**Result** ✓ Passed

- Advice** Nearside Rear Lamp broken but not showing any white light
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Lamp broken but not showing any white light
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-02-24 09:42**MOT test number** 680359743313**Result** ✓ Passed

- Advice** BOTH FRONT TYRES WEARING ON EDGES
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2017-02-17 12:47**MOT test number** 856768047791**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
15 December 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	15 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BF14KAX
Plate since	2019-03-29
Current registration	BF14KAX
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-01
Last registration	2023-11-27
Complete history	See info



Registration #1	2014-03-01	22 mi
Registration #2	2017-02-17	34.401 mi
Registration #3	2018-02-24	42.866 mi
Registration #4	2019-01-17	50.473 mi
Registration #5	2020-01-11	59.608 mi
Registration #6	2020-01-11	59.608 mi
Registration #7	2021-01-11	66.838 mi
Registration #8	2022-01-11	74.068 mi
Registration #9	2022-01-11	74.068 mi
Registration #10	2022-01-11	74.068 mi
Registration #11	2022-01-11	74.068 mi
Registration #12	2022-01-11	74.068 mi
Registration #13	2023-11-27	81.298 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2092 mm
Height	1500 mm
Length	4784 mm
Wheel base	2850 mm
Kerb weight	1396 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	EJ26323