





report date: 2024-03-28

## General information

| Make                | ТОУОТА                         |
|---------------------|--------------------------------|
| Model               | COROLLA VVTI COLOUR COLLECTION |
| Colour              | Blue                           |
| Year of manufacture | 2006                           |
| Top speed           | 118 mph                        |
| Gearbox             | 5 speed Manual                 |

# Engine & fuel consumption

| Power                   | 109 BHP             |
|-------------------------|---------------------|
| Max. torque             | 150 Nm at 4.800 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 31.4 mpg            |
| Consumption extra urban | 47.9 mpg            |
| Consumption combined    | 40.4 mpg            |
| CO2 emission            | 168 g/km            |
| CO2 label               | Н                   |



CarCheck.co.uk page 1/13



# Internet history

## Entry 1

Date 2021-10-16

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date    | 2023-11-06 |
|--------------------|------------|
|                    |            |
| MOT pass rate      | 94 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 1          |
| Total advice items | 13         |
| Total items failed | 4          |

| MOT #16   |  | 2022-11-02 14:41 |
|---|--|------------------|
| MOT test  | number   | 958916861748     |
| Result  |  | ✓ Passed         |
| Next expi   | ry date  | 2023-11-06       |
| Advice  | Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))   |                  |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |  |                  |
| Advice  | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #15   | 2021-10-16 14:00 |
|---|------------------|
| MOT test number   | 805611801600     |
| Result  | <b>✓</b> Passed  |
| Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #14** 2021-10-09 16:00

**MOT test number** 280217252751

Result X Failed

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13 2020-11-07 12:26

**MOT test number** 599391859994

**Result** ✓ Passed

**Advice** O/s/r , o/s/f , n/s/f tires worn.

**MOT #12** 2019-10-12 15:36

**MOT test number** 233946147078

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-10-13 11:37

**MOT test number** 449715137359

**Result** 
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #10  | 2017-09-19 10:59 |
|--|------------------|
| MOT test number  | 867849139230     |
| Result   | ✓ Passed         |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) |                  |

| MOT #9  | 2016-1 | 10-08 10:36 |
|---|--------|-------------|
| MOT test number   | 992    | 706117189   |
| Result  |        | ✓ Passed    |
|   |        |             |
| MOT #8  | 2015-1 | 11-14 12:18 |
| MOT test number   | 495    | 720516184   |
| Result  |        | ✓ Passed    |
|   |        |             |
| MOT #7  | 2014-1 | 10-25 11:43 |
| MOT test number   | 4183   | 278594260   |
| Result  |        | ✓ Passed    |
| Notice N/S/R & O/S/R CHILD SEAT FITTED , NOT ALLOWING FULL CHECK OF ADULTS SEAT BELT. |        |             |

| MOT #6          | 2013-11-12 13:30 |
|-----------------|------------------|
| MOT test number | 655156513302     |
| Result          | ✓ Passed         |
|                 |                  |

| MOT #5          | 2012-11-09 10:12 |
|-----------------|------------------|
| MOT test number | 827364412335     |
| Result          | ✓ Passed         |

| MOT #4          | 2011-11-11 11:17 |
|-----------------|------------------|
| MOT test number | 717005111393     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 5/13



Advice

**MD55EXT** 

report date: 2024-03-28

| MOT #3          | 2010-11-19 11:09 |
|-----------------|------------------|
| MOT test number | 852963020304     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #2          | 2009-12-21 13:49 |
| MOT test number | 451195159376     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2008-12-16 11:14 |
| MOT test number | 382801458322     |
| Result          | ✓ Passed         |
|                 |                  |

Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



#### Tax & MOT check

Tax expired: 1 October 2023



**Expired:** 6 November 2023

X MOT

| Tax status       | Expired at 1 October 2023 |
|------------------|---------------------------|
| Days left        | 212 days too late         |
| MOT expiry date  | 6 November 2023           |
| Full MOT history | See MOT history           |

#### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | Н          |
| Single payment (12 months)              | £ 290,00,- |
| Single six month payment                | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| e mier meeory   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates.   |             |
| Number of plates  | ,           |
| Current registration  | NK NK       |
| Plate since   |             |
| Current registration  | NK NK       |
| Flate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 10/13



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Registration #18

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 18         |
| First mileage registration | 2006-01-20 |
| Last registration          | 2022-11-02 |
| Complete history           | See info   |



| Registration #1  | 2006-01-20 | 26 mi     |
|------------------|------------|-----------|
| Registration #2  | 2008-12-16 | 26.375 mi |
| Registration #3  | 2009-12-21 | 32.246 mi |
| Registration #4  | 2010-11-19 | 36.974 mi |
| Registration #5  | 2011-11-11 | 42.129 mi |
| Registration #6  | 2012-11-09 | 45.831 mi |
| Registration #7  | 2013-11-12 | 49.103 mi |
| Registration #8  | 2014-10-25 | 51.676 mi |
| Registration #9  | 2015-11-14 | 54.477 mi |
| Registration #10 |            | 77.777 es |
| Registration #11 |            | 71.777 es |
| Registration #12 |            | 77.777 es |
| Registration #13 |            | 71.777 es |
| Registration #14 |            | 77.777 es |
| Registration #15 |            | 71.777 es |
| Registration #16 |            | 10.107 es |
| Registration #17 |            | 71.777 es |
|                  |            |           |

More info >

71.777 mi

CarCheck.co.uk page 12/13

7070.70.70



report date: 2024-03-28

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 60567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating | ***             |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1710 mm |
|---------------------|---------|
| Height              | 1475 mm |
| Length              | 4180 mm |
| Wheel base          | 2600 mm |
| Kerb weight         | 1220 kg |
| Max. allowed weight | 1655 kg |

# Additional information

| Fuel tank capacity                | 55 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 13/            |

Number of axles 2

Engine number 3ZZU710271