



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I20 CRDI SE
Colour	Silver
Year of manufacture	2015
Top speed	109 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 2.500 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-06-15
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-03
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #9	2023-09-04 15:28
MOT test number	276018002875
Result	✓ Passed
Next expiry date	2024-09-03
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #8	2023-09-04 14:52
MOT test number	132911858668
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #7	2022-08-04 15:49
MOT test number	502531138754
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2022-08-04 15:17**MOT test number** 763084290139**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2021-06-14 15:29**MOT test number** 778902690831**Result** ✓ Passed**MOT #4** 2021-06-10 14:53**MOT test number** 170018894589**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Brake disc contaminated (1.1.14 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brake pad(s) contaminated (1.1.13 (b))

**MOT #3** 2020-08-26 09:51**MOT test number** 155237015067**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing tyre cracking and on 3mm (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))**Advice** Rear both rear discs and pads signs of heat damage**Advice** Offside Front Tyre slightly damaged/cracking or perishing tyre cracking and on 3mm (5.2.3 (d) (ii))**MOT #2** 2019-09-18 09:49**MOT test number** 967297444376**Result** ✓ Passed**MOT #1** 2018-09-13 08:20**MOT test number** 514276741313**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	3 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 EK65KXJ
Plate since	2019-09-28
Current registration	 EK65KXJ
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-24
Last registration	2023-09-04
Complete history	See info



Registration #1	2015-09-24	18 mi
Registration #2	2018-09-13	21.262 mi
Registration #3	2019-09-18	28.021 mi
Registration #4	2020-08-26	30.987 mi
Registration #5	2021-06-10	31.863 mi
Registration #6	2021-06-14	31.863 mi
Registration #7	2023-09-04	31.863 mi
Registration #8	2023-09-04	31.863 mi
Registration #9	2023-09-04	31.863 mi
Registration #10	2023-09-04	31.863 mi
Registration #11	2023-09-04	31.863 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1280 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FCEU468065