





report date: 2024-03-29

General information

Make	AUDI	
Model	A4 TDI QUATTRO SE TECHNIK	
Colour	Grey	
Year of manufacture	2014	
Top speed	142 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	174 BHP	
Max. torque	380 Nm at 2.500 rpm	
Engine capacity	1.968 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	46.3 mpg	
Consumption extra urban	62.8 mpg	
Consumption combined	55.4 mpg	
CO2 emission	134 g/km	
CO2 label	E	



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-03 2

Pictures

Listing price View report





source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-18
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	18
Total items failed	7

MOT #10	2023-10-18 15:39
MOT test number	356684198710
Result	✓ Passed
Next expiry date	2024-10-18

MOT #9	2022-10-14 10:31
MOT test number	129183266972
Result	✓ Passed

MOT #8	2021-09-23 15:20
MOT test number	833085482160
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2020-10-19 15:07 **MOT** test number 910967620190 ✓ Passed Result **Advice** Offside Rear tyre bald on inner edge **Advice** Nearside Rear reverse light bulb inop Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and worn on edges (5.2.3 (e)) Advice Offside Front tyre wearing on edges Advice Nearside Rear Tyre slightly damaged/cracking or perishing outer wall has splits and worn on inner edge (5.2.3 (d) (ii)) **Advice** Central exhaust sleeve corroded / breaking up

MOT #6 2020-10-16 11:20

MOT test number 421186656821

Result X Failed

Advice Offside Rear tyre bald on inner edge

Advice Nearside Rear reverse light bulb inop

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and worn on edges (5.2.3 (e))

Advice Offside Front tyre wearing on edges

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Central exhaust sleeve corroded / breaking up

Advice Nearside Rear Tyre slightly damaged/cracking or perishing outer wall has splits and worn on inner edge (5.2.3 (d) (ii))

MOT #5 2019-04-25 15:35

MOT test number 471693192138

Result \rightarrow Passed

CarCheck.co.uk page 4/12



✓ Passed

MOT #4 2019-04-25 12:53

MOT test number 990768044157

Result X Failed

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #3 2018-04-26 15:15

MOT test number 731640886689

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

Advice Emissions to clean to test

Result

MOT #2 2018-04-24 11:44

MOT test number 938053878175

Result X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure Various lumps on inside of tyre (4.1.D.1b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Emissions to clean to test

Fail Nearside Front Tyre tread depth below requirements of 1.6mm Nail in Tyre, Cut to cords on inside (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm Bald on inside (4.1.E.1)

Advice Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)

MOT #1 2017-04-26 10:25

MOT test number 925870349913

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
HARMAN CO.	

Plate changes	More info >
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK.
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-01
Last registration	2023-10-18
Complete history	See info



Registration #1	2014-09-01	25 mi
Registration #2	2017-04-26	41.663 mi
Registration #3	2018-04-24	59.530 mi
Registration #4	2018-04-26	59.540 mi
Registration #5	2019-04-25	80.934 mi
Registration #6	2019-04-25	80.934 mi
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		70.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1427 mm
Length	4701 mm
Wheel base	2808 mm
Kerb weight	1565 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	63 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles 2

Engine number CGLC440151