



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.2 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-07-03
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-03-30
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	31
Total items failed	6

MOT #18	2024-03-14 14:43
MOT test number	419319229569
Result	✓ Passed
Next expiry date	2025-03-30

MOT #17	2023-03-14 09:22
MOT test number	271007206667
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
Advice	Vehicle covered in underseal

MOT #16	2022-03-17 12:06
MOT test number	702334679755
Result	✓ Passed
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15**

2021-03-31 15:50

MOT test number

730027409442

Result

✓ Passed

- Advice** Heavily undersealed
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2021-03-26 14:00

MOT test number

955342084479

Result

✗ Failed

- Fail** Rear Exhaust emissions likely to be affected by an exhaust leak backbox flange x 2 (8.2.1.1 (b))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Heavily undersealed
- Advice** Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Front Tyre has ply or cords exposed 205/55/16 (5.2.3 (d) (ii))

**MOT #13**

2020-03-10 13:49

MOT test number

431496162356

Result

✓ Passed

Advice Front Suspension component mounting prescribed area is corroded but not considered excessive +rear (5.3.6 (a) (i))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice All 4 brake disc pitted

MOT #12

2019-03-08 14:47

MOT test number

587503228530

Result

✓ Passed

Advice Under trays/sill covers/engine cover fitted

MOT #11

2019-03-07 12:50

MOT test number

838303837689

Result

✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Under trays/sill covers/engine cover fitted

MOT #10

2018-03-08 15:37

MOT test number

383991363704

Result

✓ Passed

Advice Under trays fitted

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2017-02-22 14:53**MOT test number** 527403326608**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Under trays/sill covers fitted**MOT #8** 2016-03-24 15:53**MOT test number** 148460359277**Result** ✓ Passed**Advice** Under trays fitted obscuring some components**MOT #7** 2015-04-29 14:35**MOT test number** 578689015117**Result** ✓ Passed**MOT #6** 2014-09-10 15:52**MOT test number** 399383154276**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-08-13 16:08**MOT test number** 967795723285**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Offside rear tyre worn to the legal limit**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #4	2012-08-20 11:31
MOT test number	625503932241
Result	✓ Passed
MOT #3	2011-09-13 14:59
MOT test number	119776951253
Result	✓ Passed
MOT #2	2010-09-15 14:53
MOT test number	411398950268
Result	✓ Passed
MOT #1	2009-08-25 09:39
MOT test number	330167639442
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 March 2025

Tax status		Valid until 1 November
Days left		185
MOT expiry date		30 March 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 T777JKK
Plate since	2024-03-29
Current registration	 T777JKK
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-14
Last registration	2024-03-14
Complete history	See info



Registration #1	2006-09-14	16 mi
Registration #2	2009-08-25	15.804 mi
Registration #3	2010-09-15	28.098 mi
Registration #4	2011-09-13	41.799 mi
Registration #5	2012-08-20	54.444 mi
Registration #6	2013-08-13	58.758 mi
Registration #7	2014-09-10	63.352 mi
Registration #8	2015-04-29	64.682 mi
Registration #9	2016-03-24	68.380 mi
Registration #10	2017-02-22	69.323 mi
Registration #11	2018-03-20	70.377 mi
Registration #12	2019-03-20	71.377 mi
Registration #13	2020-03-20	72.377 mi
Registration #14	2021-03-20	73.377 mi
Registration #15	2022-03-20	74.377 mi
Registration #16	2023-03-20	75.377 mi
Registration #17	2024-03-20	76.377 mi
Registration #18	2025-03-20	77.377 mi
Registration #19	2026-03-20	78.377 mi
Registration #20	2027-03-20	79.377 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430743161