





report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	М



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-08-26	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-31
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #15	2023-11-01 16:40
MOT test number	161653113362
Result	✓ Passed
Next expiry date	2024-10-31
Minor Front Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #14		2022-09-01 15:49
MOT test	number	953733649818
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Front Headlamp has a product on the lens but not seriously reducing light ou	utput (4.1.4 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #13	2021-09-02 12:56
MOT test number	536696685783
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12 2021-09-01 12:09

MOT test number 823087271103

Result X Failed

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11 2020-05-19 07:48

MOT test number 995966343099

Result Passed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2019-03-21 12:17

MOT test number 670672202558

Result

Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear arm rear bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 225/45 R18 (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge 225/45 R18 (5.2.3 (e))

MOT #9 2017-07-13 11:39

MOT test number 369825810134

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #8 2016-07-20 13:08

MOT test number 543922077689

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7 2016-07-20 09:47

MOT test number 916283534898

Result X Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #6 2015-07-24 09:44

MOT test number 387145605207

Result \(\sqrt{Passed} \)

Notice N/S/R tyre approx 2.5mm and worn inner tread area.

Notice Sill covers fitted.

MOT #5 2014-07-24 13:11

MOT test number 448005804249

Result ✓ Passed

MOT #4 2013-06-27 09:32

MOT test number 186878373175

Result ✓ Passed

MOT #3 2012-07-19 15:22

MOT test number 955991302230

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2011-07-26 11:24

MOT test number 306057301409

Result \rightarrow Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #1 2010-07-19 12:10

MOT test number 400820100256

Result ✓ Passed

CarCheck.co.uk page 6/12



GR07VVU
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK NK
Finite since	WW. PL. PI
Current registration	NK NK
Made since	
	More info >
	11010 11110 /

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-07-25
Last registration	2023-11-01
Complete history	See info



Registration #1	2007-07-25	10 mi
Registration #2	2010-07-19	20.711 mi
Registration #3	2011-07-26	27.374 mi
Registration #4	2012-07-19	34.517 mi
Registration #5	2013-06-27	46.875 mi
Registration #6	2014-07-24	62.798 mi
Registration #7	2015-07-24	83.113 mi
Registration #8	2016-07-20	98.117 mi
Registration #9	2016-07-20	98.117 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #11 Registration #12		77.777 es
-		11.777 es 11.777 es 11.777 es
Registration #12		11.777-00 11.777-00 11.777-00
Registration #12 Registration #13		77.777-66 77.777-66 77.777-66 77.777-66
Registration #12 Registration #13 Registration #14		70,777-66 70,777-66 70,777-66 70,777-66 70,777-66

More info >

CarCheck.co.uk page 11/12



GR07VVU
report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

D: 100	ensior	- C		ьь
		15 ~	wein	nı.

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1542 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	577793

CarCheck.co.uk page 12/12