



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Blue
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G





## Internet history


### Entry 4

Date	2022-11-23
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

### Entry 3

Date	2022-11-19
Pictures	41
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 2

Date	2021-12-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 1

Date	2021-06-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2024-05-25
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	27
Total items failed	0

MOT #13	2023-05-26 13:19
---------	------------------

MOT test number	881035299672
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-25
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on inner and outer edge's, 4mm (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Can't tell how deep? (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on inner and outer edge's, 4mm (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))

**MOT #12**

2023-05-26 11:27

**MOT test number**

975865279394

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge smooth on inner and outer edge's, 4mm (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- MAJOR** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge smooth on inner and outer edge's, 4mm (5.2.3 (e))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Can't tell how deep? (5.2.3 (d) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Slight (1.1.14 (a) (ii))
- MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #11**

2022-06-03 10:37

**MOT test number**

627830490481

**Result****✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2021-06-30 12:12

**MOT test number**

533067830739

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Sides (1.1.14 (a) (ii))

**MOT #9**

2020-03-09 09:24

**MOT test number**

157778231377



**MOT #8** 2019-03-05 11:10**MOT test number** 653073407977**Result** ✓ Passed**MOT #7** 2019-03-04 13:28**MOT test number** 392071529585**Result** ✗ Failed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #6** 2018-03-23 11:37**MOT test number** 727772147062**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2017-03-24 14:25**MOT test number** 440262199771**Result** ✓ Passed**Advice** Osr tyre worn on edge.**MOT #4** 2015-12-09 09:51**MOT test number** 779534182075**Result** ✓ Passed



MOT #3	2014-12-16 10:06
MOT test number	648330754385
Result	✓ Passed
MOT #2	2013-12-18 11:40
MOT test number	376792153344
Result	✓ Passed
MOT #1	2013-01-03 16:44
MOT test number	189123303097
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
25 May 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	25 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-08
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	2010-01-08	17 mi
Registration #2	2013-01-03	15.355 mi
Registration #3	2013-12-18	20.362 mi
Registration #4	2014-12-16	25.517 mi
Registration #5	2015-12-09	30.723 mi
Registration #6	2017-03-24	43.908 mi
Registration #7	2018-03-23	59.488 mi
Registration #8	2019-03-04	68.100 mi
Registration #9	2019-03-05	68.112 mi
Registration #10	2019-03-05	68.112 mi
Registration #11	2019-03-05	68.112 mi
Registration #12	2019-03-05	68.112 mi
Registration #13	2019-03-05	68.112 mi
Registration #14	2019-03-05	68.112 mi
Registration #15	2019-03-05	68.112 mi
Registration #16	2019-03-05	68.112 mi
Registration #17	2019-03-05	68.112 mi
Registration #18	2019-03-05	68.112 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 755957