





report date: 2024-03-28

General information

Make	MAZDA
Model	cx-3 D SPORT NAV
Colour	Grey
Year of manufacture	2016
Top speed	110 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	1.497 сс
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/12





Internet history

Entry 3


Date 2023-12-13

Pictures 8









source: g3remarketing.co.uk

Entry 2

2021-09-26 Date

5 **Pictures**

Listing price View report









source: cargurus.co.uk

Entry 1

Date 2021-09-24

Pictures 5

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-04
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #8	2024-01-05 17:02
MOT test number	993639151385
Result	✓ Passed
Next expiry date	2025-01-04
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened ((1.1.14 (a) (ii))
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))	
Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1)	(e))

CarCheck.co.uk page 3/12



MOT #7 2024-01-05 11:02

MOT test number 166565603150

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge On legal limit 1.6mm (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2022-12-23 11:30

MOT test number 161863697825

Result

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened slightly worn (1.1.14 (a) (ii))

Advice Nearside Front Nail in tyre

MOT #5 2021-12-15 15:03

MOT test number 890689115997

Result J Passed

CarCheck.co.uk page 4/12



× Failed

MOT #4 2020-12-23 13:47

MOT test number 536937084221

Advice

Result

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3 2020-12-23 10:30

MOT test number 797360312785

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2 2019-07-02 11:02

MOT test number 312935004616

Result ✓ Passed

MOT #1 2019-07-01 14:04

MOT test number 538113739776

Result X Failed

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure cut on inner edge , cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
manus .	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-07-01
Last registration	2024-01-05
Complete history	See info



Registration #1	2016-07-01	27 mi
Registration #2	2019-07-01	40.070 mi
Registration #3	2019-07-02	40.129 mi
Registration #4	2020-12-23	53.339 mi
Registration #5	2020-12-23	53.339 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	85%
Children	79%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1535 mm
Length	4275 mm
Wheel base	2570 mm
Kerb weight	1200 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	S530322561

CarCheck.co.uk page 12/12