



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180 K SE
Colour	Blue
Year of manufacture	2003
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	46.3 mpg
Consumption combined	33.6 mpg
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-24
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-29
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	42
Total items failed	16

MOT #22	2020-11-30 18:25
MOT test number	318616845589
Result	✓ Passed
Next expiry date	2021-11-29

**MOT #21**

2020-11-20 15:53

MOT test number

652423165550

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Engine cover and under-tray fitted not allowing full inspection on some components.
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #20

2019-11-26 12:55

MOT test number

903146016732

Result**✓ Passed**

- Advice** Both front tyres wearing inner / outer edges
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Under trays fitted
- Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
- Minor** Nearside Front Suspension component ball joint dust cover severely deteriorated (ball joint facing down) (5.3.4 (b) (i))

**MOT #19** 2018-11-24 12:53**MOT test number** 239570779603**Result** ✓ Passed**MOT #18** 2017-11-10 17:07**MOT test number** 704495399224**Result** ✓ Passed**Advice** Both outersills and under vehicle covered.**MOT #17** 2016-11-18 12:25**MOT test number** 542400013586**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Under vehicle covered**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #16** 2016-11-17 16:28**MOT test number** 947789474360**Result** ✗ Failed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Under vehicle covered**Fail** Nearside Front Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #15**

2015-11-18 16:29

MOT test number

736732530044

Result

✓ Passed

Advice Slight damage N/S front tyre outer wall.**Advice** Slight damage to O/S front top ball joint dust cover.**Advice** Both outer sills and under vehicle covered.**Advice** Slight wear to rear tyres.**MOT #14**

2015-11-18 11:10

MOT test number

307346780185

Result

✗ Failed

Advice Slight damage to O/S front top ball joint dust cover.**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Advice** Both outer sills and under vehicle covered.**Advice** Slight wear to rear tyres.**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Slight damage N/S front tyre outer wall.**MOT #13**

2014-08-01 13:39

MOT test number

767463014288

Result

✓ Passed

MOT #12

2013-08-05 15:00

MOT test number

429927513204

Result

✓ Passed

**MOT #11** 2012-09-13 08:59**MOT test number** 227357952288**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2011-09-20 12:13**MOT test number** 995233961236**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2011-09-20 09:42**MOT test number** 639313161281**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**MOT #8** 2010-09-13 15:21**MOT test number** 582416850245**Result** ✓ Passed**MOT #7** 2009-09-14 16:12**MOT test number** 323997559459**Result** ✓ Passed

**MOT #6** 2009-09-14 12:12**MOT test number** 254227259215**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #5** 2008-09-18 11:37**MOT test number** 210002668230**Result** ✓ Passed**Notice** Front number plate cracked**Notice** Rear number plate poor**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2008-09-17 12:44**MOT test number** 733621068284**Result** ✗ Failed**Fail** Offside Front Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** Front number plate cracked**Fail** Nearside Front Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear number plate poor



MOT #3	2007-09-24 11:10
MOT test number	854327667268
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2006-09-22 17:01
MOT test number	123355866230
Result	✓ Passed

MOT #1	2006-09-22 10:20
MOT test number	920265066233
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
31 October 2021

X

MOT

Expired:
29 November 2021

Tax status	Expired at 31 October 2021
Days left	912 days too late
MOT expiry date	29 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-26
Last registration	2020-11-30
Complete history	See info



Registration #1	2003-09-26	14 mi
Registration #2	2006-09-22	35.356 mi
Registration #3	2006-09-22	35.356 mi
Registration #4	2007-09-24	45.892 mi
Registration #5	2008-09-17	54.047 mi
Registration #6	2008-09-18	54.047 mi
Registration #7	2009-09-14	61.129 mi
Registration #8	2009-09-14	61.129 mi
Registration #9	2010-09-13	67.048 mi
Registration #10	2011-09-20	71.100 mi
Registration #11	2011-09-20	71.100 mi
Registration #12	2012-09-13	75.413 mi
Registration #13	2013-09-13	75.413 mi
Registration #14	2013-09-13	75.413 mi
Registration #15	2013-09-13	75.413 mi
Registration #16	2013-09-13	75.413 mi
Registration #17	2013-09-13	75.413 mi
Registration #18	2013-09-13	75.413 mi
Registration #19	2013-09-13	75.413 mi
Registration #20	2013-09-13	75.413 mi
Registration #21	2013-09-13	75.413 mi
Registration #22	2013-09-13	75.413 mi
Registration #23	2013-09-13	75.413 mi
Registration #24	2013-09-13	75.413 mi

More info >



Dimensions & weight

Width	1728 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	2715 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	27194630246172