



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC EU4
Colour	Red
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	14.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-04
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)

**MOT history****MOT #20** 2022-02-01 17:42**MOT test number** 980180083229**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDE (1.1.14 (a) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDE (1.1.14 (a) (ii))**MAJOR** Indicator switch inoperative (4.4.2 (a) (ii))**MAJOR** Front Headlamp aim projected beam image is obviously incorrect BOTH SIDE FRONT (4.1.2 (c))**MOT #19** 2020-12-10 11:45**MOT test number** 112880485281**Result** ✓ Passed**Advice** Front Track rod end ball joint has slight play both sides (2.1.3 (b) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #18** 2019-11-22 14:25**MOT test number** 704682054457**Result** ✓ Passed**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #17** 2019-11-22 14:25**MOT test number** 190083846724**Result** ✗ Failed**Pass with rectification** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))**MOT #16** 2018-10-31 11:51**MOT test number** 101967310693**Result** ✓ Passed**MOT #15** 2018-10-30 12:10**MOT test number** 172056880568**Result** ✗ Failed**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Inner Drag link end ball joint has excessive play (2.1.3 (b) (i))**MOT #14** 2017-10-28 14:03**MOT test number** 282172952538**Result** ✓ Passed

**MOT #13** 2017-10-28 12:10**MOT test number** 441175141561**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #12** 2016-10-21 14:28**MOT test number** 117021422253**Result** ✓ Passed**Advice** Engine management warning light on**Advice** Check emissions warning**Advice** Service warning**Advice** Clonk from offside front top shock mount**MOT #11** 2016-10-20 14:32**MOT test number** 727118521019**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Headlamp aim too low and too far to the left. (1.8)**Advice** Service warning**Advice** Clonk from offside front top shock mount**Fail** Rear Direction indicator incorrect colour both (1.4.A.2f)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Engine management warning light on**Advice** Check emissions warning

**MOT #10** 2015-10-19 11:13**MOT test number** 503049083246**Result** ✓ Passed**MOT #9** 2014-10-21 16:53**MOT test number** 347604194295**Result** ✓ Passed**MOT #8** 2014-09-05 16:35**MOT test number** 539378344259**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #7** 2013-09-03 14:28**MOT test number** 457456043211**Result** ✓ Passed**MOT #6** 2012-09-05 15:26**MOT test number** 925399742282**Result** ✓ Passed**MOT #5** 2011-08-09 12:36**MOT test number** 885451021200**Result** ✓ Passed**Notice** Both rear tyres side walls cracking**MOT #4** 2010-07-20 11:29**MOT test number** 524311400231**Result** ✓ Passed**Notice** Both rear tyres cracking



MOT #3	2009-07-30 12:49
MOT test number	363971319275
Result	✓ Passed

MOT #2	2008-08-04 14:09
MOT test number	321427618497
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2008-08-04 14:09
MOT test number	551037618291
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-26
Last registration	2022-02-01
Complete history	See info



Registration #1	2005-09-26	15 mi
Registration #2	2008-08-04	12.192 mi
Registration #3	2009-07-30	13.088 mi
Registration #4	2010-07-20	13.667 mi
Registration #5	2011-08-09	14.180 mi
Registration #6	2012-09-05	14.820 mi
Registration #7	2013-09-03	15.111 mi
Registration #8	2014-09-05	15.471 mi
Registration #9	2014-10-21	15.507 mi
Registration #10	2015-10-19	17.483 mi
Registration #11	2016-10-20	23.212 mi
Registration #12	2016-10-20	23.212 mi
Registration #13	2016-10-20	23.212 mi
Registration #14	2016-10-20	23.212 mi
Registration #15	2016-10-20	23.212 mi
Registration #16	2016-10-20	23.212 mi
Registration #17	2016-10-20	23.212 mi
Registration #18	2016-10-20	23.212 mi
Registration #19	2016-10-20	23.212 mi
Registration #20	2016-10-20	23.212 mi
Registration #21	2016-10-20	23.212 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D001335