



SV66TPO

report date: 2024-03-28

General information

Make	FIAT
Model	124 SPIDER MULTIAIR LUSO PLUS
Colour	White
Year of manufacture	2016
Top speed	134 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	240 Nm at 2.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-09
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #7	2024-03-08 12:59
MOT test number	327901213581
Result	✓ Passed
Next expiry date	2025-03-25
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #6	2023-03-04 10:24
MOT test number	807060323209
Result	✓ Passed

MOT #5	2022-03-26 11:32
MOT test number	348291162156
Result	✓ Passed

**MOT #4** 2022-03-18 11:03**MOT test number** 667468076633**Result** ✗ Failed**MAJOR** Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #3** 2021-07-27 06:58**MOT test number** 825585222845**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Road wheel slightly distorted inner rim distorted (5.2.2 (c) (i))**MOT #2** 2020-10-06 12:57**MOT test number** 684690739181**Result** ✓ Passed**MOT #1** 2019-10-01 15:58**MOT test number** 550397778531**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-07
Last registration	2024-03-08
Complete history	See info



Registration #1	2016-10-07	17 mi
Registration #2	2019-10-01	22.886 mi
Registration #3	2020-10-06	27.599 mi
Registration #4	2021-07-27	32.317 mi
Registration #5	2022-03-29	35.277 mi
Registration #6	2022-03-29	35.277 mi
Registration #7	2022-03-29	35.277 mi
Registration #8	2022-03-29	35.277 mi
Registration #9	2024-03-08	35.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1233 mm
Length	4054 mm
Wheel base	2310 mm
Kerb weight	1050 kg
Max. allowed weight	1315 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	2091875