





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	172 Nm at 3.200 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.5 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-19

Pictures 36

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-06
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	8
Total items failed	7

MOT #21		2024-02-07 17:26
MOT test	number	562867430832
Result		✓ Passed
Next expi	ry date	2025-02-06
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #20		2023-02-03 15:12
MOT test	number	359942315393
Result		✓ Passed
Advice back (5.3.4	Tyre slightly damaged/cracking or perishing all 4 perished (5.2.3 (d) (ii)) Offside Front Lower Suspension arm pin or bush worn but not resulting in except (a) (i))	cessive movement
Advice back (5.3.4	Nearside Front Lower Suspension arm pin or bush worn but not resulting in e 4 (a) (i))	excessive movement

MOT #19	2021-11-10 07:39
MOT test number	797217039177
Result	✓ Passed
MOT #18	2020-11-20 10:30
MOT test number	479480309664
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #17	2019-11-12 11:46
MOT test number	410639863374
Result	✓ Passed
Minor Windscreen wiper blade defective (3.4 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #16	2018-11-12 10:40
MOT test number	123204974420
Result	✓ Passed
MOT #15	2017-11-23 11:30
MOT test number	589800819365
Result	√ Passed
MOT #14	2017-11-22 16:29
MOT test number	742911142076
Result	X Failed

MOT test number	742911142070
Result	X Failed
Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	

MOT #13	2016-06-13 12:44
MOT test number	763976145972
Result	✓ Passed
MOT #12	2015-06-22 09:22
MOT test number	135963375138
Result	✓ Passed

CarCheck.co.uk page 4/13



Pass with rectification

OE04GUC

report date: 2024-03-29

MOI #11	2014-06-13 12:06
MOT test number	908924864196
Result	✓ Passed

MOT #10	2013-06-21 10:51
MOT test number	428902373170
Result	/ Passed

MOT #9 2012-06-21 14:49 936403872118 **MOT test number** Result ✓ Passed

MOT #8 2012-06-21 14:49 **MOT test number** 458583572182 Result × Failed Pass with rectification Nearside Front Direction indicators not working (1.4.A.2c) Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #7	2011-06-20 12:07
MOT test number	396831071154
Result	✓ Passed
MOT #6	2011-06-20 12:07

MOT test number 268371371491 Result × Failed

Nearside Front Direction indicators not working (1.4.A.2c)

MOT #5 2010-06-18 09:15 **MOT** test number 224059360489 Result Passed

CarCheck.co.uk page 5/13



Result

OE04GUC

report date: 2024-03-29

× Failed

MOT #4 2009-06-02 09:18

MOT test number 790663359143

Advice Front brake disc slightly pitted (3.5.1h)

MOT #3 2008-06-09 09:10

MOT test number 554991368112

Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2008-06-09 09:10

MOT test number 344021168133

Result ✓ Passed

MOT #1 2007-06-04 13:01

MOT test number 733465457154

Result ✓ Passed

CarCheck.co.uk page 6/13



OE04GUC report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



-

OE04GUC

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates.

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-05-28
Last registration	2024-02-07
Complete history	See info



Registration #1	2004-05-28	26 mi
Registration #2	2007-06-04	1.843 mi
Registration #3	2008-06-09	2.257 mi
Registration #4	2009-06-02	3.073 mi
Registration #5	2010-06-18	4.589 mi
Registration #6	2011-06-20	6.508 mi
Registration #7	2012-06-21	9.781 mi
Registration #8	2013-06-21	11.333 mi
Registration #9	2014-06-13	13.644 mi
Registration #10	2015-06-22	15.746 mi
Registration #11		11.117 es
Registration #12		71.777 es
Registration #13		11.117 es
Registration #14		71.777 es
Registration #15		11.117 es
Registration #16		71.777 es
Registration #17		11.117 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.177 es

More info >

CarCheck.co.uk page 12/13



OE04GUC report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity 55 Fuel delivery Multi-Point Injection		
Fuel delivery Multi-Point Injection	k capacity	55 I
	ivery	Multi-Point Injection
Number of doors 2	of doors	2
Number of seats 3		3

CarCheck.co.uk page 13/13

Number of axles	2

Engine number AZJ725872