





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Blue
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2021-10-24

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-23
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-16
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #14	2023-11-17 16:50
MOT test number	896700614409
Result	✓ Passed
Next expiry date	2024-11-16
Advice Nearside Front Tyre worn close to legal limit/worn on edge badly w	worn on outside edge (5.2.3 (e))

MOT #13	2023-11-08 09:34
MOT test number	228730899206
Result	× Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge badly worn on ou	itside edge (5.2.3 (e))
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	

MOT #12	2022-11-10 12:39
MOT test number	249849420479
Result	✓ Passed
Advice Items removed from driver's view prior to test	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11 2021-11-09 16:50

MOT test number 288271418225

MOT #10 2021-03-29 12:17

MOT test number 880618701654

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Wipers starting to smear screen

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9 2021-03-29 10:57

MOT test number 561881824131

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Wipers starting to smear screen

MOT #8 2020-03-19 12:39

MOT test number 309391610105

Result

Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7	2020-03-19 10:35
MOT test number	193217785320
Result	🗙 Failed
Advice Wipers starting to smear screen	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Rear Exhaust system insecure bracket broke (6.1.2 (a))	

MOT #6		2019-03-12 08:48
MOT test	number	502496353085
Result		✓ Passed
Advice	Rear Exhaust mounting defective bracket corroded (6.1.2 (a))	
Advice	Wipers starting to smear screen	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

Nearside Near Child Seat fitted flot allowing full inspection of adult beit	
MOT #5	2018-03-26 14:39
MOT test number	243829820815
Result	✓ Passed
MOT #4	2017-04-07 09:18
MOT test number	670103286807
Result	✓ Passed
MOT #3	2016-10-04 11:34
MOT test number	963581923958
Result	✓ Passed
MOT #2	2015-10-03 08:06
MOT test number	484216340213
Result	✓ Passed

CarCheck.co.uk page 5/13



Advice

Notice

BK61YDU report date: 2024-03-29

MOT test number

Result

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Exhaust rear silencer hanger broken

CarCheck.co.uk page 6/13



Tax & MOT check





Expires: 16 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
HARMAN CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2023-11-17
Complete history	See info



Registration #1	2011-09-30	18 mi
Registration #2	2014-10-08	12.826 mi
Registration #3	2015-10-03	20.381 mi
Registration #4	2016-10-04	32.327 mi
Registration #5	2017-04-07	34.716 mi
Registration #6	2018-03-26	37.102 mi
Registration #7	2019-03-12	39.487 mi
Registration #8	2020-03-19	42.731 mi
Registration #9	2020-03-19	42.731 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		0.00 44
Registration #17		11.177 ms

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1273 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number FDBV0147325