





General information

Make	KIA
Model	SOUL CRDI ECHO
Colour	Red
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E








Internet history

Entry 1	
Date	2021-09-15
Pictures	21
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	7

МОТ #16	2023-08-25 09:19
MOT test number	449624537213
Result	🗸 Passed
Next expiry date	2024-09-01
Minor Nearside Steering rack gaiter damaged or deteriorated, but preventing the in (2.1.3 (g) (i))	gress of dirt Twisted
Advice Offside Rear Brake pipe corroded, covered in grease or other material Corro	ded/pitted (1.1.11 (c))
(i)) Offside Registration plate lamp inoperative in the case of multiple lamps or lig	ght sources (4.7.1 (b)
Advice Nearside Rear Brake pipe corroded, covered in grease or other material Corr (c))	roded/pitted (1.1.11
Advice Offside Brake pipe corroded, covered in grease or other material Front to reacorroded/pitted at end (1.1.11 (c))	ar pipe
Advice Nearside Rear Tyre worn close to legal limit/worn on edge CLOSE TO LIMIT. (5.2.3 (e))





MOT #15	2023-08-25 09:19
MOT test number	986777924418
Result	🗙 Failed
Advice Offside Brake pipe corroded, covered in grease or other material Front to corroded/pitted at end (1.1.11 (c))	rear pipe
Advice Nearside Rear Tyre worn close to legal limit/worn on edge CLOSE TO LIMI	T. (5.2.3 (e))
Minor Offside Registration plate lamp inoperative in the case of multiple lamps o (i))	r light sources (4.7.1 (b)
Pass with rectificationRear Registration plate inscription illegible Tow ball hitc(Detachable hitch removed (0.1 (b))	h obscuring part of plate.
Advice Offside Rear Brake pipe corroded, covered in grease or other material Co	rroded/pitted (1.1.11 (c))
Minor Nearside Steering rack gaiter damaged or deteriorated, but preventing the (2.1.3 (g) (i))	ingress of dirt Twisted
Advice Nearside Rear Brake pipe corroded, covered in grease or other material C (c))	Corroded/pitted (1.1.11

08-17 10:29
7114792248
🗸 Passed
PIPE TO
BRAKE

MOT #13	2021-09-02 15:50
MOT test number	873932559667
Result	✓ Passed

MOT #12	2021-09-02 14:27
MOT test number	679233768052
Result	🗙 Failed
Fail Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))	





MOT #11	202	20-10-07 11:55
MOT test	number 2	207209883043
Result		🗸 Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #10	2019-10-16 10:46
MOT test number	299101215509
Result	✓ Passed

MOT #9	: 9 2019-10-3	15 10:47
MOT te	est number 740545	5668607
Result		X Failed
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4	(b) (ii))
Fail (ii))	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.	4 (b)
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #8	2018-10-17 07:23
MOT test number	785174860215
Result	✓ Passed

MOT #7	2018-10-16 11:57
MOT test number	281951575485
Result	🗸 Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2017-11-11 10:15
MOT test number	918360996906
Result	✓ Passed





MOT #5	2016-10-29 08:58
MOT test number	469654262897
Result	✓ Passed
МОТ #4	2015-11-13 15:53
MOT test number	305166655469
Result	✓ Passed
МОТ #3	2014-11-17 17:41
MOT test number	947911524334
Result	✓ Passed
MOT #2	2014-07-28 10:02
MOT test number	165559104204
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1		2014-07-28 10:02
MOT test number		958869504299
Result		🗙 Failed
Pass with rectification	Front Headlamp aim too high (1.8)	
Advice Offside Front Typ	re worn close to the legal limit (4.1.E.1)	
Pass with rectification	Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Nearside Front T	yre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed	✓ MOT
1 September 2024 Tax status	Expires: 1 September 2024 Valid until 1 September
Days left	124
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-21
Last registration	2023-08-25
Complete history	See info



Registration #1	2011-09-21	14 mi
Registration #2	2014-07-28	22.565 mi
Registration #3	2014-11-17	23.563 mi
Registration #4	2015-11-13	34.145 mi
Registration #5	2016-10-29	46.234 mi
Registration #6	2017-11-11	56.553 mi
Registration #7	2018-10-16	65.539 mi
Registration #8	2018-10-17	65.544 mi
Registration #9	2019-10-15	73.611 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		10.000 est





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1429 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBAH532535