



report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND BLUEHDI EXCLUSIVE
Colour	Blue
Year of manufacture	2016
Top speed	117 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-29
Pictures	5
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-09-23
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	10
Total items failed	7

MOT #10	2023-09-06 14:35
MOT test number	964551942683
Result	✓ Passed
Next expiry date	2024-09-23
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2023-09-06 08:33
MOT test number	637495937726
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2022-09-12 14:44
MOT test number	578586865798
Result	✓ Passed
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2022-09-09 09:41**MOT test number** 943201198847**Result** ✗ Failed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2021-09-15 15:02**MOT test number** 139976061419**Result** ✓ Passed**Advice** Nearside Front outer sill damaged**MOT #5** 2021-09-15 10:03**MOT test number** 322930904183**Result** ✗ Failed**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front outer sill damaged**MOT #4** 2020-09-24 14:56**MOT test number** 542570727742**Result** ✓ Passed**MOT #3** 2019-11-21 16:20**MOT test number** 422705577227**Result** ✓ Passed



MOT #2	2019-11-21 15:54
MOT test number	272951714886
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1	2019-05-22 08:50
MOT test number	899161646219
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
23 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-03-31
Last registration	2023-09-06
Complete history	See info



Registration #1	2016-03-31	24 mi
Registration #2	2019-05-22	16.711 mi
Registration #3	2019-11-21	19.874 mi
Registration #4	2019-11-21	19.874 mi
Registration #5	2020-09-24	32.211 mi
Registration #6	2020-09-24	32.211 mi
Registration #7	2020-09-24	32.211 mi
Registration #8	2020-09-24	32.211 mi
Registration #9	2020-09-24	32.211 mi
Registration #10	2020-09-24	32.211 mi
Registration #11	2020-09-24	32.211 mi
Registration #12	2020-09-24	32.211 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1359 kg
Max. allowed weight	2205 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBHD3039018