






report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC TDCI
Colour	White
Year of manufacture	2012
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.700 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-10

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-08-21
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	20
Total items failed	4

MOT #14	2023-08-22 12:46
MOT test number	653521594086
Result	✓ Passed
Next expiry date	2024-08-21
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #13	2022-07-13 13:05
MOT test number	555220423925
Result	✓ Passed
MOT #12	2021-08-03 16:10
MOT test number	495213975171
Result	✓ Passed
MOT #11	2021-07-14 07:55
MOT test number	848574343394
Result	X Failed
MAJOR Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #10	2020-12-09 14:31
MOT test number	423422458176
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

673865056916

Result

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))

 MOT #8
 2019-12-02 11:47

 MOT test number
 578361540461

 Result
 ✓ Passed

 MOT #7
 2018-11-22 10:31

 MOT test number
 915819287419

 Result
 ✓ Passed

 Advice
 Front Both tyres wearing on edges

MOT #6 2018-11-21 11:53 **MOT** test number 563014973428 Result × Failed **MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Front Both tyres wearing on edges **MAJOR** Exhaust emissions test aborted because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f)) **MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Both front tyre wearing on edges

MOT #4 2017-11-27 11:07 **MOT** test number 839062571199 Result **X** Failed Exhaust emits excessive smoke or vapour of any colour (7.4.B.4) Fail Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Both front tyre wearing on edges Fail Offside Rear coil spring broken (2.4.C.1a) **Advice** Play in steering rack inner joint(s) Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #3	2016-11-28 11:22
MOT test number	445564449283
Result	✓ Passed
MOT #2	2016-11-28 11:22
MOT test number	437961096728
Result	× Failed
Pass with rectification Offside Stop lamp not working (1.2.1b)	

CarCheck.co.uk page 5/13



MOT #1

MOT test number

Result

Advice Offside drive shaft seal slight leak

2015-11-19 10:35

362208163128

✓ Passed

Advice Nearside Rear tyre wearing on outer edge and slightly uneven

Advice Child seat fitted

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	hictory
Owner	HISLOLV

, ,		
For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NEW	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-04
Last registration	2023-08-22
Complete history	See info



Registration #1	2012-12-04	25 mi
Registration #2	2015-11-19	33.514 mi
Registration #3	2016-11-28	42.024 mi
Registration #4	2016-11-28	42.024 mi
Registration #5	2017-11-27	50.316 mi
Registration #6	2017-11-28	50.324 mi
Registration #7	2018-11-21	60.179 mi
Registration #8	2018-11-22	60.185 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		0.00 44
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1780 kg
Max. allowed weight	1780 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 13/13