






report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 COUPE CABRIOLET
Colour	Grey
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	190 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.0 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

F	n	r۱	,	1

ciitiy 1	
Date	2021-05-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT #20		2022-02-17 18:18
MOT test	number	594118164146
Result		✓ Passed
Next expir	ry date	2023-02-16
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Bot	th side (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in ex	cessive movement (5.3.4
(a) (i))	wearside from Suspension and pin or busin word but not resulting in ex	cessive movement (3.3.4

MOT #19		2020-10-30 15:53
MOT test	number	610445209984
Result		✓ Passed
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front fog light is insecure	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #18		2020-10-30 14:46
MOT test	number	142699456329
Result		≍ Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
MAJOR	Offside Front Headlamp light intensity severely reduced (4.1.4 (a))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front fog light is insecure	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #17

MOT test number

Result

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number
948628083877

Result

Advice
Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail
Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice
Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #14
 2017-04-21 11:00

 MOT test number
 590865623323

 Result
 ✓ Passed

 MOT #13
 2016-04-21 10:32

 MOT test number
 543081341498

 Result
 ✓ Passed

 MOT #12
 2015-03-27 09:41

 MOT test number
 169166985065

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #11 2014-04-26 10:00

MOT test number 498936014147

Result \rightarrow Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2014-04-25 15:29

MOT test number 215665714113

Result X Failed

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2013-04-05 11:26

MOT test number 568915293048

Result

Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #8 2013-04-04 12:32

MOT test number 509894193066

Result ★ Failed

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Notice Child seat fitted not allowing full inspection of adult belt

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2012-04-17 08:24

MOT test number 209928002167

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #6	2011-04-27 09:36
MOT test number	250167511440

Result ✓ Passed

MOT #5 2011-04-14 16:27

MOT test number 129014801161

Result × Failed

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #4 2010-04-21 14:27

MOT test number 634251310151

Result ✓ Passed

MOT #3 2009-04-27 17:19

MOT test number 782597019158

Result
✓ Passed

MOT #2 2009-04-14 17:54

MOT test number 313234909132

Result X Failed

Fail Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #1 2008-04-12 10:16

MOT test number 933853408131

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK AIN
Flate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-04-15
Last registration	2022-02-17
Complete history	See info



Registration #1	2005-04-15	20 mi
Registration #2	2008-04-12	14.608 mi
Registration #3	2009-04-14	19.051 mi
Registration #4	2009-04-27	19.055 mi
Registration #5	2010-04-21	23.835 mi
Registration #6	2011-04-14	27.226 mi
Registration #7	2011-04-27	27.319 mi
Registration #8	2012-04-17	30.465 mi
Registration #9	2013-04-04	33.330 mi
Registration #10	2013-04-05	33.330 mi
Registration #11	2014-04-25	36.766 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.177 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1423 mm
Length	4349 mm
Wheel base	2605 mm
Kerb weight	1457 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberLH1Z1197563