

Ford



## General information

Make	FORD	
Model S-MAX ZETEC TDCI		
Colour	Silver	
Year of manufacture	2007	
Top speed	122 mph	
0 - 60 mph	9.7 seconds	
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	138 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н







## Internet history

Entry 2

Date Pictures 2021-09-18

50

Listing price

View report



source: cargurus.co.uk

### Entry 1

Date

Pictures

Listing price

2021-07-03 50

View report



source: cargurus.co.uk













## MOT history

MOT expiry date	2023-07-04
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	20
Total items failed	6

MOT #18	2022-06-30 10:57
MOT test number	805561468841
Result	✓ Passed
Next expiry date	2023-07-04

MOT #17	2021-07-05 10:44
MOT test number	319288966709
Result	✓ Passed

MOT #16	2021-07-03 12:30
MOT test number	388363113497
Result	🗙 Failed
<b>Fail</b> Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))	

MOT #15	2020-10-28 10:18
MOT test number	930551740354
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Oil leak, but not excessive Driveshaft seal (8.4.1 (a) (i))	





MOT #14	2019-10-28 14:56
MOT test number	119669189604
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #13	2018-10-12 15:16
MOT test number	927090009116
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2018-10-12 11:32
MOT test number	829132383823
Result	🗙 Failed
FailExhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2017-10-16 10:11
MOT test number	635588698156
Result	✓ Passed
Advice Rear Child Seat fitted not allowing full inspection of adult belt x3	

MOT #10		2016-10-18 10:39
MOT test	number	650287904346
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	





MOT #9	2015-10-09 09:48
MOT test number	361123611491
Result	✓ Passed
MOT #8	2014-10-02 09:44
MOT test number	955915474269
Result	✓ Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	
<b>Notice</b> Engine covers fitted obscuring some components in the engine ba	У

MOT #7		2014-10-01 15:26
MOT test	number	476194974276
Result		🗙 Failed
Notice	Nail in offside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
<b>Fail</b> E	xhaust has a major leak of exhaust gases (7.1.2)	
Notice	Nail in nearside rear tyre	
Notice	Under-trays fitted obscuring some underside components	

MOT #6	2013-09-12 16:45
MOT test number	597735553254
Result	✓ Passed
<b>Notice</b> O/s/f tyre worn on inside edge	
Notice Centre section of exhaust rusty	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





МОТ #5	2012-10-11 09:35
MOT test number	439505682237
Result	✓ Passed
MOT #4	2012-10-10 17:23
MOT test number	688154382298
Result	🗙 Failed
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enoug (4.1.D.1a)	h to reach the ply or cords
MOT #2	2011 10 05 14.12

MOT #3		2011-10-05 14:12
MOT test numbe	er	749348371266
Result		✓ Passed
<b>Notice</b> Child	seat fitted not allowing full inspection of adult belt	

МОТ #2	2011-10-05 10:33
MOT test number	327218071425
Result	🗙 Failed
<b>Fail</b> Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
<b>Notice</b> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2010-09-02 11:44
MOT test number	763005640232
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 14 September 2022	<b>X</b> <b>MOT</b> Expired: 4 July 2023
Tax status	Expired at 14 September
Days left	592 days too late
MOT expiry date	4 July 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Carrent registration Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-12
Last registration	2022-06-30
Complete history	See info



2007-09-12	25 mi
2010-09-02	30.596 mi
2011-10-05	38.566 mi
2011-10-05	38.566 mi
2012-10-10	47.687 mi
2012-10-11	47.687 mi
2013-09-12	54.345 mi
2014-10-01	61.514 mi
2014-10-02	61.514 mi
2015-10-09	70.401 mi
2016-10-18	81.030 mi
2010 10 10	011000
2010 10 10	11.277 mg
	11.277 est 11.277 est
	11, 117, 46 11, 117, 46 11, 117, 46
	01,000 est 01,000 est 01,000 est 01,000 est
	01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
	0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
	0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
	0. 577 46 0. 577 46 0. 577 46 0. 577 46 0. 577 46 0. 577 46 0. 577 46
	0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
	2010-09-02 2011-10-05 2011-10-05 2012-10-10 2012-10-11 2013-09-12 2014-10-01 2014-10-02

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13