





report date: 2024-03-29

#### General information

Make	MAZDA
Model	CX-5 GT SPORT NAV PLUS
Colour	Black
Year of manufacture	2019
Top speed	119 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	162 BHP
Max. torque	213 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption combined	36.7 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

	_
Entry	1

Date	2022-06-13
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

### **MOT** history

MOT expiry date	2025-04-08
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #5	2024-03-25 10:25
MOT test number	404395112904
Result	✓ Passed
Next expiry date	2025-04-08
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4	2024-03-25 10:25
MOT test number	562934065419
Result	<b>×</b> Failed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	

MOT #3	2023-03-13 11:37
MOT test number	128078166555
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))  Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT** #1 2022-04-04 10:14 **MOT** test number 843360486248 Result ✓ Passed Advice Items removed from driver's view prior to test **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear Tyre slightly damaged/cracking or perishing Plus cut (5.2.3 (d) (ii)) Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 4/11



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	8 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-04-09
Last registration	2024-03-25
Complete history	See info



Registration #1	2019-04-09	17 mi
Registration #2	2022-04-04	31.718 mi
Registration #3		11.777 es
Registration #4	2023-03-13	36.780 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 mi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	78%
Safety systems	59%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1840 mm
Height	1680 mm
Length	4550 mm
Max. allowed weight	2035 kg

## Additional information

Number of seats	5
Number of axles	2
Engine number	PE 10661596

CarCheck.co.uk page 11/11