




report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D5 SE EU4
Colour	Blue
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-29
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	33
Total items failed	12

MOT #19	2023-08-01 10:34
MOT test number	558631880897
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2023-07-28 07:09
MOT test number	960943195617
Result	✗ Failed
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Minor	Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #17** 2022-07-25 08:54**MOT test number** 624571067875**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT DISCS CORRODED (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded BOTH COIL SPRING CORRODED (5.3.1 (b) (i))**MOT #16** 2021-04-12 09:14**MOT test number** 165686834966**Result** ✓ Passed**MOT #15** 2020-04-30 08:44**MOT test number** 173071306075**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))**Advice** Front Service brake fluctuating, but not excessively both side (1.2.1 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14** 2019-03-01 10:09**MOT test number** 549955322523**Result** ✓ Passed**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**MOT #13** 2018-02-21 12:00**MOT test number** 235068287333**Result** ✓ Passed



MOT #12	2017-03-01 17:00
MOT test number	708247679200
Result	✓ Passed
Advice	Nearside Rear tyre slightly worn on edge

MOT #11	2017-03-01 11:15
MOT test number	114837753528
Result	✗ Failed
Advice	Nearside Rear tyre slightly worn on edge
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Rear Brakes imbalanced across an axle (3.7.B.5b)

MOT #10	2016-03-02 13:47
MOT test number	150024061160
Result	✓ Passed
Advice	Centre ex bracket corroded

MOT #9	2015-03-02 13:11
MOT test number	416051165087
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Front front brake fluctuating, but not excessively (3.7.B.3)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2014-02-25 16:48**MOT test number** 465436154084**Result** ✓ Passed

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Notice Exhaust hanger broken but exhaust still supported

Notice Child seat fitted not allowing full inspection of adult belt

MOT #7 2014-02-24 14:57**MOT test number** 345285354056**Result** ✗ Failed

Fail Offside Front Direction indicator incorrect colour (1.4.A.2f)

Notice Exhaust hanger broken but exhaust still supported

Advice Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #6 2013-02-26 16:07**MOT test number** 959117653020**Result** ✓ Passed

**MOT #5** 2013-02-26 10:13**MOT test number** 795947653074**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #4 2012-02-14 09:35**MOT test number** 556555042047**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-02-14 14:31**MOT test number** 607385941018**Result** ✓ Passed**MOT #2** 2010-02-03 10:04**MOT test number** 193424630006**Result** ✓ Passed

- Advice** Offside Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2009-02-02 12:29
MOT test number	303693139085
Result	✓ Passed
<div>Notice</div> Windscreen wipers slightly split	



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-02-22
Last registration	2023-08-01
Complete history	See info



Registration #1	2006-02-22	28 mi
Registration #2	2009-02-02	20.799 mi
Registration #3	2010-02-03	29.829 mi
Registration #4	2011-02-14	38.383 mi
Registration #5	2012-02-14	44.787 mi
Registration #6	2013-02-26	58.700 mi
Registration #7	2013-02-26	58.700 mi
Registration #8	2014-02-24	72.561 mi
Registration #9	2014-02-25	72.713 mi
Registration #10	2015-03-02	86.704 mi
Registration #11	2016-03-02	101.185 mi
Registration #12	2016-03-02	101.185 mi
Registration #13	2016-03-02	101.185 mi
Registration #14	2016-03-02	101.185 mi
Registration #15	2016-03-02	101.185 mi
Registration #16	2016-03-02	101.185 mi
Registration #17	2016-03-02	101.185 mi
Registration #18	2016-03-02	101.185 mi
Registration #19	2016-03-02	101.185 mi
Registration #20	2016-03-02	101.185 mi
Registration #21	2016-03-02	101.185 mi
Registration #22	2016-03-02	101.185 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1519 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	417262