



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 SE
Colour	Black
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-08-08
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-30
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #13 2023-11-25 12:41

MOT test number 785358242237

Result ✓ Passed

Next expiry date 2024-11-30

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Outer Suspension component pin or bush slightly worn trailing arm bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Outer Suspension component pin or bush slightly worn trailing arm bush (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12 2022-11-09 14:12

MOT test number 618320276856

Result ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2021-11-05 15:53

MOT test number 130934631901

Result ✓ Passed

**MOT #10** 2021-11-04 12:24**MOT test number** 328879577561**Result** ✗ Failed**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #9** 2020-11-18 13:41**MOT test number** 482533559062**Result** ✓ Passed**MOT #8** 2019-11-13 12:52**MOT test number** 381481046085**Result** ✓ Passed**MOT #7** 2018-11-07 11:38**MOT test number** 282970072085**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin o/s on 1.6 (1.1.13 (a) (ii))**MOT #6** 2017-11-01 10:55**MOT test number** 227472094812**Result** ✓ Passed**MOT #5** 2016-11-10 12:23**MOT test number** 410061883887**Result** ✓ Passed



MOT #4	2016-11-09 11:20
MOT test number	877999503678
Result	✗ Failed
Advice	Offside Front headlamp self level indicator arm detached from lower arm
Fail	Supplementary Restraint System warning lamp indicates a fault (5.4.2)

MOT #3	2015-11-04 10:45
MOT test number	215926057100
Result	✓ Passed

MOT #2	2014-11-10 11:22
MOT test number	276034614304
Result	✓ Passed

MOT #1	2013-11-06 10:56
MOT test number	676120813389
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
30 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	30 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-30
Last registration	2023-11-25
Complete history	<a href="#">See info</a>



Registration #1	2010-11-30	21 mi
Registration #2	2013-11-06	23.336 mi
Registration #3	2014-11-10	32.921 mi
Registration #4	2015-11-04	41.111 mi
Registration #5	2016-11-09	50.446 mi
Registration #6	2016-11-10	50.447 mi
Registration #7	2017-11-01	59.695 mi
Registration #8	2018-11-07	66.912 mi
Registration #9	2019-11-01	74.129 mi
Registration #10	2020-11-01	81.346 mi
Registration #11	2021-11-01	88.563 mi
Registration #12	2022-11-01	95.780 mi
Registration #13	2023-11-01	102.997 mi
Registration #14	2023-11-01	110.214 mi
Registration #15	2023-11-25	117.431 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	882769