



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC 136PS
Colour	Grey
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	319 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





## Internet history

### Entry 3




Date	2021-08-06
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 2

Date	2021-08-05
Pictures	25
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 1

Date	2021-07-12
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-05-12
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	22
Total items failed	2

MOT #12	2023-05-13 07:40
MOT test number	886141756356
Result	✓ Passed
Next expiry date	2024-05-12
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11	2022-04-06 08:45
MOT test number	258419590427
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-02-24 10:46
MOT test number	352821696589
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened spring carrier (5.3.3 (b) (i))
Minor	Window damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Coil spring corroded both coils (5.3.1 (b) (i))

**MOT #9** 2020-03-05 15:33**MOT test number** 580497852875**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-03-08 15:44**MOT test number** 305740171521**Result** ✓ Passed**MOT #7** 2018-03-02 16:22**MOT test number** 332850658293**Result** ✓ Passed**MOT #6** 2018-02-28 16:57**MOT test number** 636550051353**Result** ✗ Failed**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2017-03-13 14:59**MOT test number** 569793418703**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2016-03-02 12:18**MOT test number** 121734581084**Result** ✓ Passed**MOT #3** 2015-03-21 10:51**MOT test number** 758160185029**Result** ✓ Passed

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Under-trays fitted obscuring some underside components

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #2** 2014-02-19 14:59**MOT test number** 649140854065**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2013-02-21 13:08**MOT test number** 896332553062**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	12 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>FE10UBF</b>
Plate since	2024-03-29
Current registration	<b>FE10UBF</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-27
Last registration	2023-05-13
Complete history	<a href="#">See info</a>



Registration #1	2010-03-27	10 mi
Registration #2	2013-02-21	56.035 mi
Registration #3	2014-02-19	63.416 mi
Registration #4	2015-03-21	74.168 mi
Registration #5	2016-03-02	78.278 mi
Registration #6	2017-03-13	84.929 mi
Registration #7	2018-02-28	91.420 mi
Registration #8	2018-03-02	91.420 mi
Registration #9	2019-03-02	91.420 mi
Registration #10	2019-03-02	91.420 mi
Registration #11	2019-03-02	91.420 mi
Registration #12	2019-03-02	91.420 mi
Registration #13	2019-03-02	91.420 mi
Registration #14	2019-03-02	91.420 mi
Registration #15	2019-03-02	91.420 mi
Registration #16	2019-03-02	91.420 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

AB89987