



General information

Make	FORD
Model	MONDEO ZETEC TDCI
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg







Internet history

Entry 1

Date	2021-07-24
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #15</b>	2023-02-08 09:55
<b>MOT test number</b>	675082600369
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-02-14
<b>Advice</b>	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #14</b>	2022-02-14 12:12
<b>MOT test number</b>	493376289450
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2021-02-15 08:57
<b>MOT test number</b>	135001717885
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #12</b>	2021-02-11 08:44
<b>MOT test number</b>	142990846986
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>DANGEROUS</b>	Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>DANGEROUS</b>	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
<b>MAJOR</b>	Exhaust has a major leak of exhaust gases center pipe hole (6.1.2 (a))



<b>MOT #11</b>	2020-02-04 13:31
<b>MOT test number</b>	786314029815
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #10</b>	2019-01-25 11:53
<b>MOT test number</b>	370934716851
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
<b>Advice</b>	Off side front tyre wearing outer edge
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner face (1.1.14 (a) (ii))
<b>Advice</b>	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

<b>MOT #9</b>	2019-01-25 11:53
<b>MOT test number</b>	575525020382
<b>Result</b>	✗ Failed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both sides inner face (1.1.14 (a) (ii))
<b>Advice</b>	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
<b>Pass with rectification</b>	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Advice</b>	Off side front tyre wearing outer edge
<b>Advice</b>	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

**MOT #8** 2018-01-31 16:31**MOT test number** 707441728884**Result** ✓ Passed**MOT #7** 2018-01-31 16:31**MOT test number** 386064400513**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #6** 2017-02-06 12:10**MOT test number** 819874834484**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured BOTH (1.4.A.2f)**MOT #5** 2016-01-29 09:55**MOT test number** 437300086151**Result** ✓ Passed**MOT #4** 2015-01-28 11:05**MOT test number** 398028125008**Result** ✓ Passed**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #3** 2014-01-20 14:07**MOT test number** 715830124012**Result** ✓ Passed



MOT #2	2013-04-03 11:59
MOT test number	498283193030
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Items removed from driver's view prior to test
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2013-04-02 13:31
MOT test number	816552693067
Result	✗ Failed
Notice	Items removed from driver's view prior to test
Fail	Offside Front Driver's seat insecure (6.2.A.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-25
Last registration	2023-02-08
Complete history	<a href="#">See info</a>



Registration #1	2010-05-25	26 mi
Registration #2	2013-04-02	41.472 mi
Registration #3	2013-04-03	41.472 mi
Registration #4	2014-01-20	50.758 mi
Registration #5	2015-01-28	60.396 mi
Registration #6	2016-01-29	67.260 mi
Registration #7	2017-02-06	75.180 mi
Registration #8	2018-01-31	86.676 mi
Registration #9	2018-01-31	86.676 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1505 kg
Max. allowed weight	2150 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	AM40965
---------------	---------