





report date: 2024-03-28

## General information

Make	FIAT
Model	PANDA POP
Colour	Red
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

## Entry 2

Date 2021-07-26

Pictures 16

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-07-22
Pictures	1
Listing price	View report



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-14
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	6
Total items failed	10

MOT #8	2023-09-13 08:48
MOT test number	614085212771
Result	✓ Passed
Next expiry date	2024-09-14

MOT #7	2022-08-30 10:28
MOT test number	785054167184
Result	✓ Passed

MOT #6			2022-08-30 10:28
MOT test	number		366874150976
Result			<b>X</b> Failed
Pass wit	h rectification	Offside Headlamp aim too high (4.1.2 (a))	
Pass wit	h rectification	Nearside Headlamp aim too high (4.1.2 (a))	

MOT #5	2021-09-15 11:35
MOT test number	600968065833
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT #4 2021-09-14 15:32

MOT test number 676886268009

**Result** X Failed

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**Fail** Offside Rear Brake cable damaged (1.1.15 (a))

**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-12-04 16:46

MOT test number 609577820628

Result 

Passed

**Advice** N/S/R TYRE WORN

MOT #2 2020-12-02 11:12

**MOT test number** 651888440343

Result × Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice N/S/R TYRE WORN

**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Steering rack has excessive free play detected at the steering wheel (steering rack fitted) O/S INNER BALLJOINT WORN (2.3 (a) (i))

Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2019-11-29 14:33
MOT test number 696700047696

**Result** ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 14 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

$\sim$		
Owner	hictory	7
OWITCE	1113601	1

,		
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
***************************************		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-11-11
Last registration	2023-09-13
Complete history	See info



Registration #1	2016-11-11	7 mi
Registration #2	2019-11-29	36.568 mi
Registration #3	2020-12-02	45.887 mi
Registration #4	2020-12-04	45.887 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		0.77 ss
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		19.777 mg

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

## Additional information

Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats	4	
Engine number Carcheck.co.uk	1523903 pag	e 12/12