



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 ACTIVE
Colour	Grey
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	137 Nm at 4.200 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2025-01-22
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	19
<b>Total items failed</b>	8

<b>MOT #12</b>	2024-01-23 11:57
<b>MOT test number</b>	425328300313
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-22
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #11</b>	2024-01-22 10:56
<b>MOT test number</b>	886540843781
<b>Result</b>	✗ Failed
<b>Fail</b>	Front Brake pad(s) less than 1.5 mm thick INNER X2 (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Rear Brake pad(s) less than 1.5 mm thick INNER X2 (1.1.13 (a) (ii))

<b>MOT #10</b>	2023-01-20 13:32
<b>MOT test number</b>	363104800113
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2023-01-20 13:32

**MOT test number**

966664947272

**Result****✗ Failed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8**

2022-01-11 12:12

**MOT test number**

973782587620

**Result****✓ Passed****Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement bush slightly worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear rear wiper split**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7**

2021-01-23 10:17

**MOT test number**

780043044859

**Result****✓ Passed****MOT #6**

2020-07-20 13:17

**MOT test number**

282251288369

**Result****✓ Passed****Advice** Side repeater slightly discoloured both (4.4.3 (a))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front arms rear bushes (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear All direction indicators slightly discoloured both (4.4.3 (a))

**MOT #5** 2020-07-18 08:45**MOT test number** 743375951570**Result** ✗ Failed**Advice** Side repeater slightly discoloured both (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear All direction indicators slightly discoloured both (4.4.3 (a))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both front arms rear bushes (5.3.4 (a) (i))**MOT #4** 2019-06-24 07:59**MOT test number** 566628704701**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-07-11 16:18**MOT test number** 230375489212**Result** ✓ Passed**MOT #2** 2018-07-10 14:24**MOT test number** 936811494904**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #1** 2017-07-17 14:26**MOT test number** 243509075252**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
22 January 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	22 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-22
Last registration	2024-01-23
Complete history	<a href="#">See info</a>



Registration #1	2014-11-22	23 mi
Registration #2	2017-07-17	22.232 mi
Registration #3	2018-07-10	29.335 mi
Registration #4	2018-07-11	29.338 mi
Registration #5	2019-06-24	37.423 mi
Registration #6	2020-07-18	45.350 mi
Registration #7	2020-07-20	45.351 mi
Registration #8	2020-07-20	45.351 mi
Registration #9	2020-07-20	45.351 mi
Registration #10	2020-07-20	45.351 mi
Registration #11	2020-07-20	45.351 mi
Registration #12	2020-07-20	45.351 mi
Registration #13	2020-07-20	45.351 mi
Registration #14	2020-07-20	45.351 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	90%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1306 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FAEZ043059