



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE MONACO VVT 136 E4
Colour	Green
Year of manufacture	2006
Top speed	124 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	191 Nm at 3.750 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	201 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-05-25
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-05
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	25
Total items failed	11

MOT #18	2023-10-06 14:16
MOT test number	621780193692
Result	✓ Passed
Next expiry date	2024-10-05

MOT #17	2023-09-29 07:59
MOT test number	122236235006
Result	✗ Failed
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Fail	Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #16	2022-09-30 08:18
MOT test number	605264739541
Result	✓ Passed

**MOT #15** 2021-11-14 08:46**MOT test number** 443171869627**Result** ✓ Passed**MOT #14** 2020-11-02 09:09**MOT test number** 156028236005**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Rear Brake pipe corroded, covered in grease or other material Rear axle pipes all corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-10-31 12:19**MOT test number** 719986398020**Result** ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material Rear axle pipes all corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-05-07 13:29**MOT test number** 886957133635**Result** ✓ Passed**MOT #11** 2018-07-24 08:42**MOT test number** 155550360217**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2017-08-23 09:15**MOT test number** 860590719331**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake pipe slightly corroded across rear axle (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly slight noise from top bearing when steering locked side to side (2.5.B.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-08-05 10:56**MOT test number** 386185312874**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2016-08-03 15:50**MOT test number** 220856334212**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2015-08-04 08:39**MOT test number** 583346574814**Result** ✓ Passed**Advice** Child seats fitted to both rear seats**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2014-08-15 15:12**MOT test number** 475627224249**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2013-08-10 10:13**MOT test number** 646702623264**Result** ✓ Passed**MOT #4** 2012-08-18 12:56**MOT test number** 236901732265**Result** ✓ Passed



MOT #3	2011-08-23 16:50
MOT test number	389905231420
Result	✓ Passed
MOT #2	2010-08-24 11:15
MOT test number	723076030240
Result	✓ Passed
MOT #1	2009-08-19 15:16
MOT test number	604611139227
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
5 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	5 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>PN56LZC</b>
Plate since	2024-03-28
Current registration	<b>PN56LZC</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-30
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2006-09-30	18 mi
Registration #2	2009-08-19	18.233 mi
Registration #3	2010-08-24	24.064 mi
Registration #4	2011-08-23	29.905 mi
Registration #5	2012-08-18	35.415 mi
Registration #6	2013-08-10	45.511 mi
Registration #7	2014-08-15	51.953 mi
Registration #8	2015-08-04	55.546 mi
Registration #9	2016-08-03	62.562 mi
Registration #10	2016-08-05	62.562 mi
Registration #11	2016-08-05	62.562 mi
Registration #12	2016-08-05	62.562 mi
Registration #13	2016-08-05	62.562 mi
Registration #14	2016-08-05	62.562 mi
Registration #15	2016-08-05	62.562 mi
Registration #16	2016-08-05	62.562 mi
Registration #17	2016-08-05	62.562 mi
Registration #18	2016-08-05	62.562 mi
Registration #19	2016-08-05	62.562 mi
Registration #20	2016-08-05	62.562 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

C054400