





report date: 2024-03-28

General information

| Make | MERCEDES-BENZ |
|---------------------|-----------------------|
| Model | CLS CLS220 D AMG LINE |
| Colour | Grey |
| Year of manufacture | 2016 |
| Top speed | 138 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 174 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.400 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 1


Date 2022-02-10

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-01-28 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 6 |
| Failed MOT tests | 0 |
| Total advice items | 7 |
| Total items failed | 0 |

| MOT #6 | | 2024-01-13 09:31 |
|-----------|---|--------------------|
| MOT test | number | 889443298649 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-28 |
| Advice | Nearside Front side repeater light intensity. Still working just not as bright as C |)/S. |
| Advice | Rear Child Seat fitted not allowing full inspection of adult belt Both sides. | |
| Advice | Front exhaust clamp and flexi weld's corroded. | |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn.235/ | /35R19 (5.2.3 (e)) |

| MOT #5 | | 2023-01-17 09:23 |
|----------|---|------------------|
| MOT test | number | 362490011347 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2022-01-21 13:32 |
|-----------------|------------------|
| MOT test number | 436453385896 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #3 | 2021-01-29 10:33 |
|---|------------------|
| MOT test number | 957280500044 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| 2020-01-29 15:28 |
|------------------|
| 197617934456 |
| ✓ Passed |
| |
| 2019-03-26 12:32 |
| 122891833975 |
| ✓ Passed |
| |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 28 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

| For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here. | |
|---|-------------|
| ********* | |
| | |
| *************************************** | |
| ******** | |
| | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | OK OK |
| Plate since | |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courte et info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-07-28 |
| Last registration | 2024-01-13 |
| Complete history | See info |



| Registration #1 | 2016-07-28 | 9 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-03-26 | 28.301 mi |
| Registration #3 | 2020-01-29 | 33.080 mi |
| Registration #4 | 2021-01-29 | 47.170 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 81% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 1881 mm |
|---------------------|---------|
| Height | 1418 mm |
| Length | 4937 mm |
| Wheel base | 2874 mm |
| Kerb weight | 1790 kg |
| Max. allowed weight | 2275 kg |

Additional information

| Fuel tank capacity | 59 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| CarChack co.uk | nago 11/11 |

CarCheck.co.uk page 11/11

| Number of seats | 4 |
|-----------------|----------------|
| Number of axles | 2 |
| Engine number | 65192433518103 |