



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I TR
Colour	Silver
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1	
Date	2022-01-15
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-17
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	30
Total items failed	8

MOT #20	2024-01-18 14:14
MOT test number	186086362507
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-01-09 14:51
MOT test number	776161093268
Result	✓ Passed
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18**

2022-01-10 11:59

**MOT test number**

437337641343

**Result**

✓ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17**

2021-03-01 13:22

**MOT test number**

599605169103

**Result**

✓ Passed

**Advice** Offside front tyre outer wall cracking**MOT #16**

2020-03-02 10:12

**MOT test number**

225329042753

**Result**

✓ Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2019-02-05 09:39

**MOT test number**

937505002775

**Result**

✓ Passed

**Advice** Nearside front shock absorber has a slight leak**Advice** Various body damage**Advice** Offside front tyre outer wall cracking**Advice** \*\* semi-auto clutch slipping heavily \*\*

**MOT #14** 2019-02-05 09:39**MOT test number** 307859398804**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside front tyre outer wall cracking**Advice** \*\* semi-auto clutch slipping heavily \*\***Advice** Nearside front shock absorber has a slight leak**Advice** Various body damage**MOT #13** 2018-02-08 17:17**MOT test number** 170091955676**Result** ✓ Passed**MOT #12** 2017-02-14 13:52**MOT test number** 648847738557**Result** ✓ Passed**MOT #11** 2017-02-13 17:49**MOT test number** 295907326113**Result** ✗ Failed**Advice** Nearside number plate light dim**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #10** 2016-02-22 11:22**MOT test number** 626624784829**Result** ✓ Passed

**MOT #9** 2016-02-22 09:47**MOT test number** 783566796522**Result** ✗ Failed**Advice** Rear brake pads wearing thin**Advice** Front brake pads wearing thin**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2015-02-25 13:52**MOT test number** 539066055052**Result** ✓ Passed**Notice** Tracking recommended**MOT #7** 2015-02-25 10:45**MOT test number** 567676455036**Result** ✗ Failed**Notice** \*\*\* offside front tyre worn very close to legal limit 205/55/16 \*\*\***Notice** Tracking recommended**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** \*\*\* both rear tyres heavily offshape \*\*\***MOT #6** 2014-02-25 13:02**MOT test number** 728706554086**Result** ✓ Passed**Notice** Both rear tyres inner edges offshape

**MOT #5** 2014-02-25 10:45**MOT test number** 198156554075**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Both rear tyres inner edges offshape**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #4** 2013-02-27 16:01**MOT test number** 366718553008**Result** ✓ Passed**MOT #3** 2012-02-02 14:00**MOT test number** 275693732031**Result** ✓ Passed**MOT #2** 2011-02-03 12:12**MOT test number** 866034931006**Result** ✓ Passed**MOT #1** 2010-02-26 14:30**MOT test number** 564307250091**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GC07XXX
Plate since	2024-03-29
Current registration	GC07XXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-01
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	6 mi
Registration #2	2010-02-26	23.033 mi
Registration #3	2011-02-03	30.813 mi
Registration #4	2012-02-02	36.360 mi
Registration #5	2013-02-27	42.589 mi
Registration #6	2014-02-25	47.798 mi
Registration #7	2014-02-25	47.798 mi
Registration #8	2015-02-25	51.057 mi
Registration #9	2015-02-25	51.057 mi
Registration #10	2016-02-22	57.286 mi
Registration #11	2016-02-22	57.286 mi
Registration #12	2016-02-22	57.286 mi
Registration #13	2016-02-22	57.286 mi
Registration #14	2016-02-22	57.286 mi
Registration #15	2016-02-22	57.286 mi
Registration #16	2016-02-22	57.286 mi
Registration #17	2016-02-22	57.286 mi
Registration #18	2016-02-22	57.286 mi
Registration #19	2016-02-22	57.286 mi
Registration #20	2016-02-22	57.286 mi
Registration #21	2016-02-22	57.286 mi
Registration #22	2016-02-22	57.286 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

**Engine number**

1ZZU896971