



RENAULT

STI4U0V

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg





Internet history

Entry 2

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	43
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

**MOT history**

<b>MOT #8</b>	2021-12-04 10:27
<b>MOT test number</b>	748627987280
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-03
<b>Advice</b>	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
<b>Advice</b>	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #7</b>	2021-12-04 10:27
<b>MOT test number</b>	802064801865
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #6</b>	2020-11-30 15:59
<b>MOT test number</b>	118018022137
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2020-06-09 14:20
<b>MOT test number</b>	370555664898
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Nail in tyre
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2019-05-24 10:31**MOT test number** 986575547138**Result** ✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3** 2018-04-05 11:35**MOT test number** 372232216666**Result** ✓ Passed**MOT #2** 2018-04-05 11:35**MOT test number** 118669677742**Result** ✗ Failed

- Pass with rectification** Offside Front Outer Front constant velocity joint is insecure (2.5.C.1b)

**MOT #1** 2017-04-10 09:34**MOT test number** 811319933374**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-28
Current registration	*****
Plate since	2019-06-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-16
Last registration	2021-12-04
Complete history	<a href="#">See info</a>



Registration #1	2014-06-16	13 mi
Registration #2	2017-04-10	10.374 mi
Registration #3	2018-04-05	16.402 mi
Registration #4	2018-04-05	16.402 mi
Registration #5	2019-05-24	29.575 mi
Registration #6	2020-06-09	40.133 mi
Registration #7	2021-12-04	40.133 mi
Registration #8	2021-12-04	40.133 mi
Registration #9	2021-12-04	40.133 mi
Registration #10	2021-12-04	40.133 mi
Registration #11	2021-12-04	40.133 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D292824