





report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ-L
Colour	Red
Year of manufacture	2017
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-15

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-28
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #5	2023-09-22 07:48
MOT test number	106789785162
Result	✓ Passed
Next expiry date	2024-09-28

MOT #4		2022-09-27 07:38
MOT test	number	260441246397
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3	2021-09-29 15:08
MOT test number	286400370875
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice
Oil change lamp on

Advice
Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice
Tyre pressure warning lamp on

Advice
Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-01-23 11:09 906753861681 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Oil change lamp on **DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Tyre pressure warning lamp on **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax expired: 23 January 2024



Expires: 28 September 2024

Tax statusExpired at 23 January 2024Days left97 days too lateMOT expiry date28 September 2024

Full MOT history See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		h:at	
-C)V	vner	misi	or

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
manage of the same	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-01-26
Last registration	2023-09-22
Complete history	See info



Registration #1	2017-01-26	25 mi
Registration #2	2020-01-23	36.000 mi
Registration #3	2020-01-23	36.000 mi
Registration #4		71.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11,177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	945 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	K12B-2069638

CarCheck.co.uk page 11/11