



report date: 2024-03-29

General information

Make	MINI
Model	PACEMAN COOPER SD ALL4
Colour	White
Year of manufacture	2014
Top speed	121 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	57.7 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 3

Date	2022-05-07
Pictures	35
Listing price	View report



source: [cargurus.co.uk](#)

Entry 2

Date	2021-07-06
Pictures	14
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-20
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #11	2023-10-31 09:43
MOT test number	612122562328
Result	✓ Passed
Next expiry date	2024-10-30

MOT #10	2023-05-09 08:53
MOT test number	204497057352
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9	2022-05-09 09:36
MOT test number	921906418714
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8	2021-10-21 14:12
MOT test number	468547038724
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2021-10-20 15:35**MOT test number** 290930530616**Result** ✗ Failed**Fail** Offside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2020-12-01 09:32**MOT test number** 743417321392**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front windscreen got small chips in swept area**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2019-12-02 15:11**MOT test number** 535659439911**Result** ✓ Passed**MOT #4** 2018-12-07 16:09**MOT test number** 679998348636**Result** ✓ Passed**MOT #3** 2018-12-07 16:09**MOT test number** 412555871097**Result** ✗ Failed**Pass with rectification** Headlamp aim too far to the right (4.1.2 (a))



MOT #2	2018-08-02 12:11
MOT test number	145349438348
Result	✓ Passed

MOT #1	2017-08-18 11:48
MOT test number	382997202460
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
5 March 2024

✓

MOT

Expires:
30 October 2024

Tax status	Expired at 5 March 2024
Days left	54 days too late
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-24
Last registration	2023-10-31
Complete history	See info



Registration #1	2014-09-24	14 mi
Registration #2	2017-08-18	29.705 mi
Registration #3	2018-08-02	41.643 mi
Registration #4	2018-12-07	42.866 mi
Registration #5	2018-12-07	42.866 mi
Registration #6	2019-12-02	46.744 mi
Registration #7	2020-12-01	52.616 mi
Registration #8	2020-12-01	52.616 mi
Registration #9	2020-12-01	52.616 mi
Registration #10	2020-12-01	52.616 mi
Registration #11	2020-12-01	52.616 mi
Registration #12	2020-12-01	52.616 mi
Registration #13	2020-12-01	52.616 mi
Registration #14	2020-12-01	52.616 mi
Registration #15	2020-12-01	52.616 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1395 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	71588967