





report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI ENDURANCE EDITION BLUE DRIVE
Colour	Black
Year of manufacture	2018
Top speed	126 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



RV18VWK
report date: 2024-03-29

Internet history

	-	4.	M3 /	- 1
ᆮ	п	ш	ľV	- 1

Elitiy 1	
Date	2021-11-19
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-11
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #5	2023-10-17 13:52
MOT test number	115008391446
Result	✓ Passed
Next expiry date	2024-11-11
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened N	Nearside & Offside (1.1.14 (a)
Advice Front Registration plate deteriorated but not likely to be misread (0.1	1 (b))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened I Warped (1.1.14 (a) (ii))	Nearside & Offside Slightly
Advice Rear Brake pad(s) wearing thin Nearside & Offside (1.1.13 (a) (ii))	

MOT #4		2022-11-02 11:27
MOT test	number	288352625470
Result		✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing both n/s and o/s (5.2.3 (d) (ii))	
Advice	Front and rear Brake disc's has slight lip	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2022-11-02 10:19

MOT test number 644638674163

Result X Failed

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front and rear Brake disc's has slight lip

Advice Rear Tyre slightly damaged/cracking or perishing both n/s and o/s (5.2.3 (d) (ii))

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

DANGEROUS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #2 2021-11-12 15:25

MOT test number 682021824733

Result ✓ Passed

MOT #1 2021-03-16 09:50

MOT test number 764324425539

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 11 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

faste since

RV18VWK

report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

UK UK

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-26
Last registration	2023-10-17
Complete history	See info



Registration #1	2018-03-26	22 mi
Registration #2	2021-03-16	40.681 mi
Registration #3	2021-11-12	45.063 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.117 es

More info >

CarCheck.co.uk page 10/11



RV18VWK
report date: 2024-03-29

Car features

The HYUNDAI	factory car options	list is only availa	able in the premium	report.

S0225 Air conditioning

S0295

S0482

S0501

\$0566 \$0567

S0569

View the complete HYUNDAI factory list for this vehicle <u>here</u>.

More info >

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number D4HBHU580487