



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CARAVELLE T30 SHUTTLE SE LWB 130TDI
Colour	Silver
Year of manufacture	2007
Top speed	102 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.461 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	29.4 mpg
CO2 emission	251 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-08-05
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-10
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	18
Total items failed	4

MOT #17	2024-03-11 15:35
MOT test number	106842544105
Result	✓ Passed
Next expiry date	2025-03-10

MOT #16	2024-03-11 09:19
MOT test number	880638442238
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15	2023-03-11 16:00
MOT test number	641655466935
Result	✓ Passed
Minor	Front Lower Suspension component ball joint dust cover severely deteriorated Nearside & offside (5.3.4 (b) (i))
Advice	Rear exhaust slightly corroded

MOT #14	2022-05-26 13:59
MOT test number	705716024815
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2022-05-25 10:48**MOT test number** 988539792246**Result** ✗ Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12 2021-06-03 13:04**MOT test number** 565489763320**Result** ✓ Passed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2021-06-03 13:04**MOT test number** 541196467076**Result** ✗ Failed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #10**

2020-06-15 08:34

MOT test number

770881233946

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #9

2019-03-07 14:53

MOT test number

140219935404

Result

✓ Passed

Minor Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #8

2018-03-13 12:32

MOT test number

930371899467

Result

✓ Passed

MOT #7

2016-08-05 15:23

MOT test number

945672591206

Result

✓ Passed

Advice O/s/f tyre down to 3mm

Advice Front brake pads getting low

**MOT #6** 2015-07-24 15:20**MOT test number** 588095705236**Result** ✓ Passed**MOT #5** 2015-07-24 12:36**MOT test number** 389595605257**Result** ✗ Failed

Fail Nearside Front Upper Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #4 2014-07-28 14:57**MOT test number** 666379404290**Result** ✓ Passed**MOT #3** 2013-07-08 15:42**MOT test number** 289229183495**Result** ✓ Passed**MOT #2** 2011-06-22 14:33**MOT test number** 327763271181**Result** ✓ Passed**MOT #1** 2010-07-07 15:14**MOT test number** 731278080129**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
10 March 2025

Tax status		Valid until 1 October
Days left		156
MOT expiry date		10 March 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YN57EYT
Plate since	2019-03-29
Current registration	 YN57EYT
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-06
Last registration	2024-03-11
Complete history	See info



Registration #1	2007-09-06	23 mi
Registration #2	2010-07-07	15.418 mi
Registration #3	2011-06-22	19.482 mi
Registration #4	2013-07-08	24.199 mi
Registration #5	2014-07-28	25.855 mi
Registration #6	2015-07-24	30.593 mi
Registration #7	2015-07-24	30.593 mi
Registration #8	2016-08-05	37.677 mi
Registration #9	2018-03-13	38.413 mi
Registration #10	2019-03-07	42.776 mi
Registration #11	2020-03-07	45.277 mi
Registration #12	2021-03-07	45.277 mi
Registration #13	2022-03-07	45.277 mi
Registration #14	2023-03-07	45.277 mi
Registration #15	2024-03-07	45.277 mi
Registration #16	2025-03-07	45.277 mi
Registration #17	2026-03-07	45.277 mi
Registration #18	2027-03-07	45.277 mi
Registration #19	2028-03-07	45.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	4890 mm
Kerb weight	2200 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9

Number of axles

2

Engine number

BNZ083256