



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S D V50
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-04
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	36
Total items failed	8

MOT #17	2023-06-24 08:09
MOT test number	576860086929
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Engine covers and under trays fitted
Advice	Exhaust system corroded, centre and rear box outer skins breaking apart
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16	2023-06-24 08:09
MOT test number	913160865476
Result	✗ Failed
Advice	Engine covers and under trays fitted
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Exhaust system corroded, centre and rear box outer skins breaking apart

**MOT #15**

2022-06-25 09:43

MOT test number

521034171341

Result

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Exhaust system corroded and rear centre box outer skin breaking apart
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Engine covers and under trays fitted

MOT #14

2022-06-25 08:09

MOT test number

407809419648

Result

✗ Failed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Exhaust system corroded and rear centre box outer skin breaking apart
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing badly age cracked almost to extent of cords/ply becoming visible (5.2.3 (d) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Engine covers and under trays fitted

MOT #13

2021-07-01 13:43

MOT test number

701088586739

Result

✓ Passed

**MOT #12** 2020-10-22 15:47**MOT test number** 681123719202**Result** ✓ Passed**Advice** Rear exhaust box and mounts deteriorating**MOT #11** 2019-11-13 10:50**MOT test number** 934945015561**Result** ✓ Passed**Advice** N/s front lower wishbone rear bush perrishing**Advice** N/s o/s front tyres uneven wear**MOT #10** 2019-11-08 15:05**MOT test number** 596124370357**Result** ✗ Failed**Advice** N/s front lower wishbone rear bush perrishing**Fail** Offside Front Suspension arm pin or bush excessively worn lower rear wishbone bush (5.3.4 (a) (i))**Advice** N/s o/s front tyres uneven wear**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MOT #9** 2018-10-26 11:48**MOT test number** 382990615645**Result** ✓ Passed**MOT #8** 2017-11-04 12:17**MOT test number** 160665889731**Result** ✓ Passed

**MOT #7** 2016-11-04 15:30**MOT test number** 294277460191**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Sill covers fitted**Advice** Covers fitted to engine bay**Advice** Both front tyres are wearing on the inside**MOT #6** 2015-11-02 17:14**MOT test number** 870276962584**Result** ✓ Passed**Advice** Sill covers fitted**Advice** Engine covers fitted**MOT #5** 2015-11-02 16:30**MOT test number** 410816728511**Result** ✗ Failed**Advice** Engine covers fitted**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Sill covers fitted**MOT #4** 2014-10-31 11:18**MOT test number** 835884704324**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2014-10-31 09:21
MOT test number	625194704392
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)

MOT #2	2013-11-16 11:40
MOT test number	527180723311
Result	✓ Passed
Notice	Seal covers fitted
Notice	O/s/r tyre perished
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2012-09-13 12:19
MOT test number	926037752285
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-12
Last registration	2023-06-24
Complete history	See info



Registration #1	2009-09-12	11 mi
Registration #2	2012-09-13	27.175 mi
Registration #3	2013-11-16	33.262 mi
Registration #4	2014-10-31	40.140 mi
Registration #5	2014-10-31	40.140 mi
Registration #6	2015-11-02	45.329 mi
Registration #7	2015-11-02	45.329 mi
Registration #8	2016-11-04	54.876 mi
Registration #9	2017-11-04	70.258 mi
Registration #10	2018-10-26	92.856 mi
Registration #11	2019-06-20	95.377 mi
Registration #12	2019-06-20	95.377 mi
Registration #13	2019-06-20	95.377 mi
Registration #14	2019-06-20	95.377 mi
Registration #15	2019-06-20	95.377 mi
Registration #16	2019-06-20	95.377 mi
Registration #17	2019-06-20	95.377 mi
Registration #18	2019-06-20	95.377 mi
Registration #19	2019-06-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1519 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	565929
---------------	--------