



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D SE (115BHP) S40
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	67.3 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-07-03
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	18
Total items failed	11

MOT #24	2023-06-09 15:21
MOT test number	399040144446
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Offside Front brake pipe has corrosion
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #23	2023-06-02 15:11
MOT test number	313375584962
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front brake pipe has corrosion
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))



MOT #22	2022-06-09 14:17
MOT test number	566262099993
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-06-09 09:40
MOT test number	447321864971
Result	✗ Failed
Fail	Brake pedal has insufficient reserve travel (1.1.2 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear second light

MOT #20	2021-06-30 16:21
MOT test number	620619443821
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19	2021-06-30 14:27
MOT test number	533478351050
Result	✗ Failed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Rear Brake pipe excessively corroded Front to rear (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18** 2020-07-13 15:41**MOT test number** 466157909984**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #17** 2020-07-13 08:31**MOT test number** 401258616807**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #16** 2019-06-18 11:26**MOT test number** 744382955494**Result** ✓ Passed**MOT #15** 2018-06-22 12:58**MOT test number** 976666156037**Result** ✓ Passed**MOT #14** 2018-06-21 14:55**MOT test number** 758346877627**Result** ✗ Failed**Fail** Nearside Rear Brake hose porous (1.1.12 (e))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Fail** Offside Front Brake hose porous (1.1.12 (e))**Fail** Offside Rear Brake hose porous (1.1.12 (e))

**MOT #13** 2017-07-03 13:51**MOT test number** 320412310778**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated slight cracking (3.6.B.4d)**MOT #12** 2016-06-20 12:29**MOT test number** 139409098014**Result** ✓ Passed**MOT #11** 2016-06-20 12:29**MOT test number** 366585191998**Result** ✗ Failed**Pass with rectification** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #10** 2015-07-06 15:09**MOT test number** 105097585181**Result** ✓ Passed**MOT #9** 2014-07-16 12:01**MOT test number** 286767394437**Result** ✓ Passed**MOT #8** 2013-07-16 10:00**MOT test number** 949377493179**Result** ✓ Passed**MOT #7** 2012-07-17 11:55**MOT test number** 599869692115**Result** ✓ Passed



MOT #6	2011-07-15 11:23
---------------	------------------

MOT test number	466816091186
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-07-26 12:16
---------------	------------------

MOT test number	554987100209
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-07-15 12:12
---------------	------------------

MOT test number	981686099145
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-07-16 11:37
---------------	------------------

MOT test number	351268898163
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-08-14 11:01
---------------	------------------

MOT test number	853696227213
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2007-08-14 11:01
---------------	------------------

MOT test number	113746827287
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Headlamp aim too low (1.8)
--------------------------------	-------------------------------------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-06-30
Last registration	2023-06-09
Complete history	See info



Registration #1	2004-06-30	24 mi
Registration #2	2007-08-14	15.760 mi
Registration #3	2008-07-16	17.333 mi
Registration #4	2009-07-15	18.885 mi
Registration #5	2010-07-26	21.300 mi
Registration #6	2011-07-15	23.140 mi
Registration #7	2012-07-17	24.573 mi
Registration #8	2013-07-16	25.509 mi
Registration #9	2014-07-16	26.364 mi
Registration #10	2015-07-06	27.387 mi
Registration #11	2016-06-20	28.003 mi
Registration #12	2016-06-20	28.003 mi
Registration #13	2017-07-03	28.681 mi
Registration #14	2018-06-20	29.359 mi
Registration #15	2019-06-20	30.037 mi
Registration #16	2020-06-20	30.715 mi
Registration #17	2021-06-20	31.393 mi
Registration #18	2022-06-20	32.071 mi
Registration #19	2023-06-09	32.749 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		
Registration #24		
Registration #25		



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1716 mm
Height	1422 mm
Length	4516 mm
Wheel base	2562 mm
Kerb weight	1225 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Engine number	F9QTC092803