





General information

Make	VOLKSWAGEN
Model	POLO SE DSG
Colour	Grey
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	11.9 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E







Internet history	
Entry 3	
Date	2021-12-22
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 2	
Date	2021-05-22
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-28
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	23
Total items failed	7

MOT #17	2023-12-28 13:24
MOT test number	408506290358
Result	✓ Passed
Next expiry date	2024-12-28
Advice Vehicle is Heavily Under-sealed.	
Advice Under-chassis, Suspension, Exhaust & Brake components corroded.	
Advice Engine Covers / Under-trays Fitted	

MOT #16	2022-12-29 15:47
MOT test number	739424765894
Result	✓ Passed
AdviceBoth front outer track rod end rubbers have perishedAdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2021-12-23 08:09
MOT test number	190193981346
Result	✓ Passed

MOT #14	2021-05-08 08:34
MOT test number	189575867912
Result	✓ Passed





MOT #13	2020-08-11 08:22
MOT test number	797938928143
Result	✓ Passed
MOT #12	2020-08-11 08:22
MOT test number	500553360946
Result	× Failed
Pass with rectification inop (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of a single lamp or all lamps both
MOT #11	2019-08-16 10:16
MOT test number	872595994897
Result	✓ Passed
MOT #10	2019-08-16 10:16
MOT test number	312724193239
Result	× Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
МОТ #9	2018-08-20 11:43
MOT test number	936801406320
Result	✓ Passed
Advice Offside Rear coil	l spring corroded
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))
Advice Nearside Front S	Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice Offside Rear tyre	e mishaped and perished
Advice Nearside Front t	yre perished
Advice Exhaust corrode	d



MOT #8	2018-08-20 10:23
MOT test number	319922022789
Result	🗙 Failed
Fail Front Headlamp not working on dipped beam both (4.1.1 (a) (ii))	
Advice Offside Rear tyre mishaped and perished	
Fail Front Headlamp aim not tested both (4.1.2 (b))	
Advice Nearside Front tyre perished	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Exhaust corroded	
Fail Front Headlamp levelling device inoperative both note unable to test (4.1.5 (a))	
Advice Offside Rear coil spring corroded	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect	t (5.3.2 (b))

MOT #7	2017-08-24 10:35
MOT test number	141644315182
Result	✓ Passed
Advice Offside Rear Tyre tread is perished + small cuts in tread.	

МОТ #6	2017-08-23 15:48	
MOT test number	852500363512	
Result	🗙 Failed	
FailNearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall.(4.1.D.1b)		
Advice Offside Rear Tyre tread is perished + small cuts in tread.		
Fail Fuel cap/sealing device sealing washer deteriorated (7.2.4c)		

HN59DJZ

report date: 2024-03-29





MOT #5		2017-01-23 11:46
MOT test	number	309542895438
Result		✓ Passed
Advice	Offside Rear inner edge of tyre feathering	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Inner fuel cap sealing ring perished starting to split	

MOT #4	2016-01-12 10:00
MOT test number	240841201651
Result	✓ Passed

MOT #3	2015-01-12 17:39
MOT test number	375932715079
Result	✓ Passed
Notice Both front tyres wearing on edges	

MOT #2	2014-01-11 11:44
MOT test number	896711414007
Result	✓ Passed
MOT #1	2013-01-16 11:44

MOT test number	999076913005
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 May 2024	Expires: 28 December 2024
Tax status	Valid until 1 May
Days left	2
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-23
Last registration	2023-12-28
Complete history	See info



Registration #1	2010-01-23	11 mi
Registration #2	2013-01-16	23.695 mi
Registration #3	2014-01-11	32.519 mi
Registration #4	2015-01-12	41.021 mi
Registration #5	2016-01-12	48.344 mi
Registration #6	2017-01-23	52.984 mi
Registration #7	2017-08-23	56.213 mi
Registration #8	2017-08-24	56.213 mi
Registration #9	2018-08-20	65.163 mi
Registration #10	2018-08-20	65.163 mi
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.777 mi
Registration #20		10. 200 aug
Registration #20		







Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1104 kg
Max. allowed weight	1580 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CGG 325933