



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D3 ES
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 3

Date	2022-07-30
Pictures	13
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-10-01
Pictures	4
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-30
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	31
Total items failed	3

MOT #13	2024-02-01 16:08
MOT test number	679078967061
Result	✓ Passed
Next expiry date	2025-02-09
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2024-02-01 09:51
MOT test number	731352803592
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2023-02-10 10:06**MOT test number** 750560362293**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear most (5.3.4 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear most (5.3.4 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-07-20 13:39**MOT test number** 155024269280**Result** ✓ Passed**MOT #9** 2021-11-09 15:46**MOT test number** 550903977399**Result** ✓ Passed**MOT #8** 2020-09-14 09:40**MOT test number** 329056053106**Result** ✓ Passed**MOT #7** 2019-09-23 11:49**MOT test number** 757361130674**Result** ✓ Passed

**MOT #6** 2018-09-18 13:14**MOT test number** 468134924276**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2017-09-14 09:03**MOT test number** 236957876849**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2016-09-13 11:53**MOT test number** 467246376913**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #3** 2015-09-24 11:21**MOT test number** 141924144563**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear TYRE NAILED
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear CHILD SEATS FITTED NOT ALLOWING FULL INSPECTION OF BELTS
- Advice** ENGINE COVERS AND LOWER COVERS FITTED NOT ALLOWING FULL INSPECTION OF COMPONENTS

MOT #2 2014-09-18 17:04**MOT test number** 159351764274**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #1 2014-09-18 11:29**MOT test number** 348191364232**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Under-trays fitted obscuring some underside components
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Prop-shaft flange bolt(s) loose/missing
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-30
Last registration	2024-02-01
Complete history	See info



Registration #1	2011-09-30	25 mi
Registration #2	2014-09-18	24.070 mi
Registration #3	2014-09-18	24.071 mi
Registration #4	2015-09-24	30.387 mi
Registration #5	2016-09-13	37.445 mi
Registration #6	2017-09-14	44.854 mi
Registration #7	2018-09-18	49.665 mi
Registration #8	2019-09-23	53.554 mi
Registration #9	2020-09-14	56.847 mi
Registration #10	2021-09-23	56.847 mi
Registration #11	2022-09-23	56.847 mi
Registration #12	2023-09-23	56.847 mi
Registration #13	2024-09-23	56.847 mi
Registration #14	2025-09-23	56.847 mi
Registration #15	2026-09-23	56.847 mi
Registration #16	2027-09-23	56.847 mi
Registration #17	2028-09-23	56.847 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1012435