



report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Black
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-25
Pictures	9
Listing price	View report



We hpi check
our vehicles



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-13
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	20
Total items failed	5

MOT #20	2023-08-14 14:18
MOT test number	627042992542
Result	✓ Passed
Next expiry date	2024-08-13
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19	2022-12-09 16:06
MOT test number	813830027334
Result	✓ Passed
Advice	Front Coil spring corroded Both front (5.3.1 (b) (i))

MOT #18	2022-08-30 14:25
MOT test number	608156319050
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt osr/nsr

**MOT #17** 2022-08-30 12:06**MOT test number** 703821231171**Result** ✗ Failed**Minor** Offside Front Inner Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt clip broken (2.1.3 (g) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt osr/nsr**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #16** 2021-09-09 16:29**MOT test number** 931122529992**Result** ✓ Passed**MOT #15** 2021-09-09 11:03**MOT test number** 359860162424**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #14** 2020-08-25 11:59**MOT test number** 127827240494**Result** ✓ Passed**MOT #13** 2019-08-28 11:17**MOT test number** 710194217668**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both side. (5.2.3 (e))

**MOT #12** 2019-08-28 11:17**MOT test number** 100829757090**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Front Tyre worn close to legal limit/worn on edge both side. (5.2.3 (e))**MOT #11** 2018-08-17 11:07**MOT test number** 929088309240**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MOT #10** 2017-08-29 12:32**MOT test number** 500643851574**Result** ✓ Passed**MOT #9** 2017-03-14 16:38**MOT test number** 304209518024**Result** ✓ Passed**MOT #8** 2016-03-12 10:35**MOT test number** 317091813885**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-03-14 10:24**MOT test number** 848083175051**Result** ✓ Passed

**MOT #6** 2014-03-15 11:57**MOT test number** 947614574072**Result** ✓ Passed**MOT #5** 2013-03-16 12:35**MOT test number** 438145773057**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-03-16 10:42**MOT test number** 486795973035**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-03-10 11:31**MOT test number** 628800972095**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-03-09 16:38**MOT test number** 825979662073**Result** ✗ Failed**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)



MOT #1	2011-03-25 10:54
MOT test number	978064481081
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
13 August 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-31
Last registration	2023-08-14
Complete history	See info



Registration #1	2008-03-31	8 mi
Registration #2	2011-03-25	12.384 mi
Registration #3	2012-03-09	15.218 mi
Registration #4	2012-03-10	15.223 mi
Registration #5	2013-03-16	18.197 mi
Registration #6	2013-03-16	18.197 mi
Registration #7	2014-03-15	20.927 mi
Registration #8	2015-03-14	23.751 mi
Registration #9	2016-03-12	26.252 mi
Registration #10	2017-03-14	28.175 mi
Registration #11	2017-08-29	29.623 mi
Registration #12	2018-03-20	31.557 mi
Registration #13	2018-03-20	31.557 mi
Registration #14	2018-03-20	31.557 mi
Registration #15	2018-03-20	31.557 mi
Registration #16	2018-03-20	31.557 mi
Registration #17	2018-03-20	31.557 mi
Registration #18	2018-03-20	31.557 mi
Registration #19	2018-03-20	31.557 mi
Registration #20	2018-03-20	31.557 mi
Registration #21	2018-03-20	31.557 mi
Registration #22	2018-03-20	31.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618