



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Black
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-08
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	35
Total items failed	2

MOT #14	2023-06-16 13:16
MOT test number	545415440837
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded both side (5.3.1 (b) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2023-06-16 13:16

**MOT test number**

367352646367

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #12**

2022-06-18 13:29

**MOT test number**

765642308124

**Result****✓ Passed****Advice** Rear Shock absorbers has light misting of oil Both side (5.3.2 (b))**Advice** Rear Suspension components corroded**MOT #11**

2021-06-22 13:33

**MOT test number**

486804417301

**Result****✓ Passed**

**MOT #10**

2020-07-22 08:17

**MOT test number**

324909035247

**Result**

✓ Passed

**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2019-08-01 09:08

**MOT test number**

924948436430

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2018-08-02 12:12

**MOT test number**

511276268554

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2017-07-13 08:21

**MOT test number**

634457663701

**Result**

✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #6** 2016-08-05 11:17**MOT test number** 722602123360**Result** ✓ Passed**Advice** Exhaust slightly corroded**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-08-04 07:37**MOT test number** 178243599165**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Exhaust slightly corroded**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #4** 2015-08-05 11:59**MOT test number** 396507215451**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside Rear Tyre Wearing On Inner Edge**MOT #3** 2014-07-29 10:16**MOT test number** 226590814289**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** Emissions too clean for printout**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2013-07-31 10:17
MOT test number	659602313214
Result	✓ Passed

MOT #1	2012-07-23 09:33
MOT test number	915095402223
Result	✓ Passed

**Notice** Rear discs slightly scored



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
21 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	21 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>AG09PHU</b>
Plate since	2019-06-29
Current registration	 <b>AG09PHU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-08-07
Last registration	2023-06-16
Complete history	<a href="#">See info</a>



Registration #1	2009-08-07	29 mi
Registration #2	2012-07-23	48.180 mi
Registration #3	2013-07-31	54.776 mi
Registration #4	2014-07-29	60.398 mi
Registration #5	2015-08-05	64.773 mi
Registration #6	2016-08-04	73.030 mi
Registration #7	2016-08-05	73.032 mi
Registration #8	2017-07-13	78.789 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 497918