



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI DSG
Colour	Silver
Year of manufacture	2007
Top speed	126 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





## Internet history

### Entry 3

Date	2021-10-16
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

### Entry 2

Date	2021-10-15
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

### Entry 1

Date	2021-08-26
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-20
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	15
Total items failed	4

MOT #19	2023-09-22 11:04
MOT test number	535322073912
Result	✓ Passed
Next expiry date	2024-10-20

MOT #18	2022-10-05 11:01
MOT test number	877719021514
Result	✓ Passed
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #17	2021-10-21 13:04
MOT test number	756237359902
Result	✓ Passed

MOT #16	2021-02-03 10:26
MOT test number	810457848575
Result	✓ Passed

MOT #15	2020-01-24 14:21
MOT test number	394013005609
Result	✓ Passed

**MOT #14** 2020-01-24 09:44**MOT test number** 446158799076**Result** ✗ Failed

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #13** 2019-01-29 09:02**MOT test number** 875361646365**Result** ✓ Passed**MOT #12** 2018-01-25 10:45**MOT test number** 353238554875**Result** ✓ Passed**MOT #11** 2018-01-25 08:15**MOT test number** 180608266265**Result** ✗ Failed

**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #10** 2017-01-27 09:10**MOT test number** 594838727047**Result** ✓ Passed

**Advice** Emission tested and no reading recorded

**Advice** Nearside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Front Inner Tyre worn close to the legal limit both (4.1.E.1)

**MOT #9** 2016-01-20 09:52**MOT test number** 905820201999**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-01-13 10:12**MOT test number** 725403715053**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-01-13 09:09**MOT test number** 565013615075**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-01-21 12:59**MOT test number** 186431324022**Result** ✓ Passed**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-01-23 12:25**MOT test number** 598553223077**Result** ✓ Passed

**MOT #4** 2013-01-23 12:25**MOT test number** 139963523443**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)**MOT #3** 2012-01-27 09:14**MOT test number** 207947422083**Result** ✓ Passed**MOT #2** 2011-02-04 14:14**MOT test number** 427515631080**Result** ✓ Passed**Advice** Inner Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Inner Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-02-09 13:54**MOT test number** 650090640053**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
20 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	20 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LE56CCY</b>
Plate since	2019-06-29
Current registration	<b>LE56CCY</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-02-10
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2007-02-10	24 mi
Registration #2	2010-02-09	17.505 mi
Registration #3	2011-02-04	23.367 mi
Registration #4	2012-01-27	29.929 mi
Registration #5	2013-01-23	33.627 mi
Registration #6	2014-01-21	37.765 mi
Registration #7	2015-01-13	41.424 mi
Registration #8	2015-01-13	41.427 mi
Registration #9	2016-01-20	44.568 mi
Registration #10	2017-01-27	45.418 mi
Registration #11	2018-01-25	48.163 mi
Registration #12	2019-01-22	51.277 mi
Registration #13	2019-01-22	51.277 mi
Registration #14	2019-01-22	51.277 mi
Registration #15	2019-01-22	51.277 mi
Registration #16	2019-01-22	51.277 mi
Registration #17	2019-01-22	51.277 mi
Registration #18	2019-01-22	51.277 mi
Registration #19	2019-01-22	51.277 mi
Registration #20	2019-01-22	51.277 mi
Registration #21	2019-01-22	51.277 mi
Registration #22	2019-01-22	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BMM 107521