



report date: 2024-03-28

General information

Make	NISSAN
Model	X-TRAIL DCI TEKNA
Colour	Black
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-15
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	67
Total items failed	20

MOT #16 2023-10-06 10:02

MOT test number 372037452986

Result ✓ Passed

Next expiry date 2024-10-05

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear back plate insecure

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15 2023-09-26 11:02

MOT test number 368486922615

Result ✗ Failed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Rear back plate insecure

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #14	2022-09-16 17:06
MOT test number	591601046370
Result	✓ Passed
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights

MOT #13	2022-09-16 11:47
MOT test number	496257421336
Result	✗ Failed
Advice	Vehicles internal headlight adjuster altered to recheck lights
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12**

2021-09-29 14:18

MOT test number

817926630213

Result

✓ Passed

- Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))
- Advice** Rear wiper blade deteriorated
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material nearside and offside (1.1.11 (c))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))
- Advice** Rear chassis and underbody corroded
- Advice** Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.12 (f) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2021-09-28 08:26

MOT test number

199251740697

Result**✗ Failed**

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Fail Offside Front Outer Drive shaft joint excessively worn (6.1.7 (c) (i))

Advice Rear chassis and underbody corroded

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))

Advice Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.12 (f) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear wiper blade deteriorated

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Parking brake lever travel high, requires adjustment

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material nearside and offside (1.1.11 (c))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2020-10-02 07:49

MOT test number

598283467228

Result

✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

2020-09-29 15:20

MOT test number

543707533625

Result

✗ Failed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail

Offside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail

Offside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))

Fail

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #8

2019-09-25 10:37

MOT test number

986833409125

Result

✓ Passed

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear Child Seat fitted not allowing full inspection of adult belt Both

**MOT #7** 2019-09-21 11:39**MOT test number** 503163356277**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt Both
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

MOT #6 2018-09-17 15:02**MOT test number** 177586471677**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2017-09-12 12:45**MOT test number** 901895221188**Result** ✓ Passed**MOT #4** 2017-09-11 11:15**MOT test number** 474243907174**Result** ✗ Failed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #3** 2016-07-26 13:38**MOT test number** 170825734289**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2015-08-04 13:08**MOT test number** 265586815271**Result** ✓ Passed

- Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #1 2014-08-06 15:03**MOT test number** 407628914289**Result** ✓ Passed

- Notice** Nail in offside rear tyre
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-08-15
Last registration	2023-10-06
Complete history	See info



Registration #1	2011-08-15	23 mi
Registration #2	2014-08-06	75.856 mi
Registration #3	2015-08-04	99.369 mi
Registration #4	2016-07-26	119.505 mi
Registration #5	2017-09-11	127.765 mi
Registration #6	2017-09-12	127.769 mi
Registration #7	2018-09-17	134.021 mi
Registration #8	2019-09-21	138.992 mi
Registration #9	2019-09-25	138.992 mi
Registration #10	2019-09-25	138.992 mi
Registration #11	2019-09-25	138.992 mi
Registration #12	2019-09-25	138.992 mi
Registration #13	2019-09-25	138.992 mi
Registration #14	2019-09-25	138.992 mi
Registration #15	2019-09-25	138.992 mi
Registration #16	2019-09-25	138.992 mi
Registration #17	2019-09-25	138.992 mi
Registration #18	2019-09-25	138.992 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1700 mm
Length	4635 mm
Wheel base	2630 mm
Kerb weight	1615 kg
Max. allowed weight	2170 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	001437
---------------	--------