





report date: 2024-03-28

General information

| Make | CITROEN |
|---------------------|----------------------------------|
| Model | C4 PICASSO BLUEHDI FEEL S/S EAT6 |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 117 mph |
| 0 - 60 mph | 11.2 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 65.7 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 100 g/km |
| CO2 label | А |



CarCheck.co.uk page 1/11



Internet history

Entry 2


| Date | 2021-10-01 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

Entry 1

| Date | 2021-09-30 | |
|---------------|-------------|--|
| Pictures | 5 | |
| Listing price | View report | |









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-02-01 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 12 |
| Total items failed | 0 |

| MOT #5 | | 2024-01-31 14:50 |
|--|---|------------------|
| MOT test number | | 307842038148 |
| Result | | ✓ Passed |
| Next expiry date | | 2025-02-01 |
| Advice Rear Exha | ust mounting defective (6.1.2 (a)) | |
| Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | | |
| Advice Nearside F | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |

| MOT #4 | | 2023-02-02 17:39 |
|----------|---|------------------|
| MOT test | number | 439897511685 |
| Result | | ✓ Passed |
| Advice | Central Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i | i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



PL66JTZ

report date: 2024-03-28

MOT #3 2021-11-16 09:47

MOT test number 431460509989

MOT #2 2021-01-14 14:57

MOT test number 853215739256

Result

Passed

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-01-06 15:46

MOT test number 360845423676

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 1 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| * | | |
|--|-----------|-------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively. | | OEN |
| *************************************** | | |
| *************************************** | | |
| ************* | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | 0.0.0 |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-01-31 |
| Last registration | 2024-01-31 |
| Complete history | See info |



| Registration #1 | 2017-01-31 | 6 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-01-06 | 22.309 mi |
| Registration #3 | 2021-01-14 | 26.591 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** | |
|-------------|------|--|
|-------------|------|--|

Video <u>see crash video</u>

Dimensions & weight

| Width | 1826 mm |
|---------------------|---------|
| Height | 1625 mm |
| Length | 4428 mm |
| Wheel base | 2785 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1975 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBHD3066007 |

CarCheck.co.uk page 11/11