





### General information

Make	LAND ROVER
Model	RANGE ROVER SD4 PRESTIGE
Colour	White
Year of manufacture	2013
Top speed	121 mph
0 - 100 km/h	9.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	174 g/km
CO2 label	Н





# Internet history

Entry	1	

Date Pictures 2021-05-26

8

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2025-01-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	21
Total items failed	4

MOT #11	2024-01-09 11:50
MOT test number	319471849415
Result	✓ Passed
Next expiry date	2025-01-19

MOT #10	2023-01-18 09:37
MOT test number	595078727808
Result	✓ Passed

МОТ #9	2022-01-06 16:08
MOT test number	866329229083
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2022-01-06 09:24
MOT test number	167145904515
Result	🗙 Failed
FailRear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #7		2021-01-20 11:56
MOT test	number	139248223352
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (	5.2.3 (e))
Advice	Items removed from driver's view prior to test	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #6 20	021-01-19 16:43
MOT test number	165851741419
Result	🗙 Failed
<b>Fail</b> Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Items removed from driver's view prior to test	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges (5.2.3	(e))
Advice Spare tyre defective	
Fail         Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #5	2019-12-17 15:11
MOT test number	181341799458
Result	Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #4	2019-12-17 10:21
MOT test number	839540700143
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm 0mm on edges	(5.2.3 (e))
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Offside Front Tyre has ply or cords exposed Ply exposed. (5.2.3 (d) (ii))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3		2018-12-19 11:07
MOT test	number	278215381416
Result		✓ Passed
Advice	<b>dvice</b> Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front tyre worn on inner edge	

MOT #2	2017-12-05 12:51
MOT test number	148925168862
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit On 3mm (4.1.E.1)	
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Front Tyre worn close to the legal limit On 2mm (4.1.E.1)	

MOT #1	2016-12-19 13:02
MOT test number	964366458843
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 19 January 2025
Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	
Category	 AMPLI
Туре	W CON

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

********	
and the second se	
*******	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	

Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	1000-20-20
	More info >





### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-30
Last registration	2024-01-09
Complete history	See info



Registration #1	2013-12-30	18 mi
Registration #2	2016-12-19	24.475 mi
Registration #3	2017-12-05	37.877 mi
Registration #4	2018-12-19	40.910 mi
Registration #5	2019-12-17	42.832 mi
Registration #6	2019-12-17	42.833 mi
Registration #7	2021-01-19	46.493 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		





# Safety ratings

NCAP rating	****
Adult	86%
Children	75%
Pedestrian	41%
Safety systems	86%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	2125 mm
Height	1640 mm
Length	4355 mm
Wheel base	2660 mm
Kerb weight	1685 kg
Max. allowed weight	2350 kg
Additional information	
Additional information Fuel tank capacity	58 I
	58 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5