





report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-28


Internet history


Entry 1

Date 2022-08-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



AF64GRK report date: 2024-03-28

	. ~ -				
M	\mathbf{O}	Γh	ici	t۸	rv/
- 14			10	LU	ΙY

MOT expiry date	2024-08-27
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	17
Total items failed	11

MOT #10		2023-08-28 13:22
MOT test	number	328847286833
Result		✓ Passed
Next expi	ry date	2024-08-27
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge bald edge (5.2.3 (e))	
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #9 2023-08-28 11:34 **MOT** test number 279083822753 Result **X** Failed Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Offside Front Headlamp aim unable to be tested (4.1.2 (b)) **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge bald edge (5.2.3 (e)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii)) Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) Advice Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2022-08-23 16:28
MOT test number	458064085941
Result	✓ Passed
MOT #7	2021-12-17 12:09
MOT test number	857481615694
Result	✓ Passed

MOT #6 2020-12-22 10:04

MOT test number 256298426927

Result \(\sqrt{Passed} \)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Fail Offside Front Headlamp aim not tested due to offside headlamp not working. (4.1.2 (b))

MOT #4

MOT test number

Result

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2018-09-28 14:30
MOT test number	581334789262
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #2

AF64GRK

report date: 2024-03-28

2018-09-24 11:17

Result

Fail Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Headlamp aim too high (4.1.2 (a))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2017-09-25 15:05

MOT test number 641591588708

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



AF64GRK report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

\sim	vner	L :	-4-	
- DV	vnar	nı	CTA	T ()

For how long did the current and previous owner(s) have this LAND ROVER? How many on ROVER have? Check it in the premium report and see all owner registrations. Download to	

2000000	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	NK SALES OF THE SA
Plate since	
Current registration	IR SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2023-08-28
Complete history	See info



Registration #1	2014-09-30	26 mi
Registration #2	2017-09-25	27.705 mi
Registration #3	2018-09-24	38.999 mi
Registration #4	2018-09-28	39.155 mi
Registration #5	2019-09-16	50.729 mi
Registration #6	2020-12-22	57.940 mi
Registration #7		11.777 es
Registration #8		111.7777 ess
Registration #9		11.777 es
Registration #10		111.7777 ess
Registration #11		13.337 esi
Registration #12		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT

CarCheck.co.uk page 13/13