




report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI SPORTIVE
Colour	White
Year of manufacture	2014
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-05
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-27
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	29
Total items failed	2

MOT #10	2023-07-17 16:04
MOT test number	208172342483
Result	✓ Passed
Next expiry date	2024-07-27
Minor	Nearside Side repeater lens defective which has no effect on emitted light Door mirror side repeater lens cracked and damaged (4.4.1 (b) (i))
Minor	Nearside Front Headlamp lens slightly defective Lens starting to discolour and deteriorate, also condensation inside headlamp lens and 1 lamp mounting broken but headlamp still secure (4.1.1 (b) (i))
Minor	Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface Reflector damaged (4.8.1 (a) (i))
Minor	Offside Front Headlamp lens slightly defective Lens starting to discolour and deteriorate (4.1.1 (b) (i))

MOT #9	2023-07-17 12:32
MOT test number	309724203864
Result	✗ Failed

Minor Nearside Front Headlamp lens slightly defective Lens starting to discolour and deteriorate, also condensation inside headlamp lens and 1 lamp mounting broken but headlamp still secure (4.1.1 (b) (i))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface Reflector damaged (4.8.1 (a) (i))

Minor Offside Front Headlamp lens slightly defective Lens starting to discolour and deteriorate (4.1.1 (b) (i))

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

Minor Nearside Side repeater lens defective which has no effect on emitted light Door mirror side repeater lens cracked and damaged (4.4.1 (b) (i))

**MOT #8**

2022-07-18 09:52

MOT test number

598882375207

Result

✓ Passed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output
Headlamp lens starting to discolour/deteriorate (4.1.4 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge Wearing slightly on edges (5.2.3 (e))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output
Headlamp lens starting to discolour/deteriorate (4.1.4 (b))

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface Less than
50% missing and cracked/damaged (4.8.1 (a) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #7

2021-07-16 13:12

MOT test number

197424013106

Result

✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect Light misting of oil
(5.3.2 (b))

Minor Nearside Front Side repeater lens defective which has no effect on emitted light Side repeater lens
broken (4.4.1 (b) (i))

MOT #6

2021-07-16 13:12

MOT test number

273400456229

Result

✗ Failed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect Light misting of oil
(5.3.2 (b))

Minor Nearside Front Side repeater lens defective which has no effect on emitted light Side repeater lens
broken (4.4.1 (b) (i))

Pass with rectification Nearside Front Side repeater incorrect colour (4.4.3 (a))

**MOT #5** 2020-07-28 14:59**MOT test number** 677375226926**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Side repeater lens has sharp edges on lens.**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #4** 2020-07-27 15:07**MOT test number** 354311190184**Result** ✗ Failed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**DANGEROUS** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Side repeater lens has sharp edges on lens.**MOT #3** 2019-07-15 09:25**MOT test number** 385412802791**Result** ✓ Passed**Advice** Offside Front Macpherson strut top bearing feels rough when turned from lock to lock**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Starting to wear on inside edge of tread (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Starting to wear on inside edge of tread (5.2.3 (e))**MOT #2** 2018-07-11 15:32**MOT test number** 551262886555**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #1	2017-07-21 16:18
MOT test number	807397772635
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KE14ZKG
Plate since	2019-06-29
Current registration	 KE14ZKG
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-31
Last registration	2023-07-17
Complete history	See info



Registration #1	2014-07-31	28 mi
Registration #2	2017-07-21	23.695 mi
Registration #3	2018-07-11	34.477 mi
Registration #4	2019-07-15	45.339 mi
Registration #5	2020-07-27	54.030 mi
Registration #6	2020-07-28	54.030 mi
Registration #7	2020-07-29	54.030 mi
Registration #8	2020-07-30	54.030 mi
Registration #9	2020-07-31	54.030 mi
Registration #10	2020-08-01	54.030 mi
Registration #11	2020-08-02	54.030 mi
Registration #12	2020-08-03	54.030 mi

More info >



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005566978 LN9