





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI TRENDLINE 4MOTION
Colour	White
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.250 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	36.2 mpg
CO2 emission	197 g/km
CO2 label	J



CarCheck.co.uk page 1/11



## Internet history


### Entry 2

Date	2021-06-17
Pictures	0
Listing price	View report

#### source: autotrader.co.uk

#### Entry 1

Date	2021-06-15	
Pictures	13	
Listing price	View report	









source: autotrader.co.uk

CarCheck.co.uk page 2/11



## MOT history

MOT expiry date	2024-01-20
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	7
Total items failed	10

MOT #7	2023-01-06 09:56
MOT test number	471878384040
Result	<b>✓</b> Passed
Next expiry date	2024-01-20

MOT #6	2022-01-21 16:17
MOT test number	957829732770
Result	✓ Passed
Minor Offside Registration plate lar	mp inoperative in the case of multiple lamps or light sources (4.7.1 (b)
Advice Main beam LED bulbs fitted	i

CarCheck.co.uk page 3/11



**MOT #5** 

YJ66LCZ report date: 2024-03-28

2022-01-17 10:44

**MOT test number** 469821323086

**Result** X Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Items removed from driver's view prior to test

Advice Main beam LED bulbs fitted

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Pass with rectification Offside Headlamp aim too high and too far to the left. (4.1.2 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

MOT #4 2021-01-13 08:24

**MOT test number** 347129581158

**Result** ✓ Passed

**MOT #3** 2021-01-12 09:44

MOT test number 197910349508

**Result** X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



MOT #2

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



More info >

## Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
**************************************	
***************************************	
***********	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	NK.
Plate since	

CarCheck.co.uk page 8/11



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-14
Last registration	2023-01-06
Complete history	See info



Registration #1	2016-10-14	26 mi
Registration #2	2020-01-16	59.985 mi
Registration #3	2020-01-16	59.985 mi
Registration #4	2021-01-12	64.900 mi
Registration #5	2021-01-13	64.910 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea 11.777 ea
•		11.77 es 11.77 es
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	see crash video



## Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CNFB052551

CarCheck.co.uk page 11/11